



CONSTRUCTION EQUIPMENT

GILBERT BLACK VOLVO L90H 624683 - REAR AXLE



Sample No: VC450397
Oil Type: TRANSAXLE OIL SAE 75W80
Job No: GILBERT BLACK



CHADWICK-BAROSS INC
 ROUTE106 237 SHEEP DAVIS ROAD
 CONCORD, NH
 US 03301
 Contact: Dan Godfrey
 godfreyd@chadwick-baross.com
 T: (603)224-4063
 F: (603)224-3001



SAMPLE INFORMATION

Sample Number	VC450397	---	---	---
Sample Date	31 Aug 2023	---	---	---
Machine Hours	7195	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Not Chngd	---	---	---
Sample Status	NORMAL	---	---	---



OIL CONDITION

Visc @ 40°C	cSt	█ 42.7	---	---	---
-------------	-----	--------	-----	-----	-----



CONTAMINATION

Silicon	ppm	█ 15	---	---	---
Sodium	ppm	█ 9	---	---	---
Potassium	ppm	█ 0	---	---	---



WEAR METALS

Iron	ppm	█ 51	---	---	---
Copper	ppm	█ 4	---	---	---
Lead	ppm	█ <1	---	---	---
Tin	ppm	█ <1	---	---	---
Aluminum	ppm	█ 2	---	---	---
Chromium	ppm	█ <1	---	---	---
Molybdenum	ppm	█ 1	---	---	---
Nickel	ppm	█ 0	---	---	---
Titanium	ppm	<1	---	---	---
Silver	ppm	0	---	---	---
Manganese	ppm	█ <1	---	---	---
Vanadium	ppm	<1	---	---	---



ADDITIVES

Calcium	ppm	█ 4204	---	---	---
Magnesium	ppm	█ 19	---	---	---
Zinc	ppm	█ 1667	---	---	---
Phosphorus	ppm	█ 1281	---	---	---
Barium	ppm	█ 0	---	---	---
Boron	ppm	█ 151	---	---	---

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: VOLVO0049
Unique No: 10633746
Signed: Doug Bogart
Report Date: 08 Sep 2023



CONSTRUCTION EQUIPMENT



GRAPHS

