CONSTRUCTION EQUIPMENT SPM595374 SENNEBOGEN 860 860.0.1095 - FRONT AXLE

| Sample No: | VCP413955 |
|------------|--------------------|
| Oil Type: | GEAR OIL SAE 80W90 |
| Job No: | SPM595374 |

VOLVO

Chromium

Nickel

Silver

Titanium

Manganese

Vanadium

Calcium

Zinc

Barium

Boron

Magnesium

Phosphorus

Molybdenum

ppm

ADDITIVES

SAMPLE INFORMATION VCP413955 Sample Number Sample Date 28 Aug 2023 Machine Hours 10929 Oil Hours 0 Oil Changed Changed NORMAL Sample Status **OIL CONDITION** Visc @ 40°C cSt 185 CONTAMINATION Silicon ppm 2 Sodium 5 ppm Potassium 0 🔲 ppm WEAR METALS Iron ppm 20 Copper ppm 10 Lead ppm 0 🔲 Tin ppm 0 🔲 Aluminum ppm **||** <1



ALTA EQUIPMENT CO - ORLAND PARK

5000 INDUSTRIAL HWY GARY, IN US 46406 Contact: DAVE ENG DAVE.ENG@ALTG.COM T: (312)350-2560 F:

Diagnosis

Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

| Depot: | VOLVO8885 |
|--------------|---------------|
| Unique No: | 10634524 |
| Signed: | Don Baldridge |
| Report Date: | 08 Sep 2023 |

Report Id: VOLVO8885 [WUSCAR] 05943912 (Generated: 09/08/2023 14:54:34) Rev: 1

■ <1

0 🔲

0

0

2

0

11

3

8

1008

305


0

1 🗌

CONSTRUCTION EQUIPMENT



VOLVO



Report Id: VOLVO8885 [WUSCAR] 05943912 (Generated: 09/08/2023 14:54:37) Rev: 1

Contact/Location: DAVE ENG - VOLVO8885