CONSTRUCTION EQUIPMENT JJ SPRAGUE HITACHI EX450LC-5 16CP007812 - COOLANT

Sample No:VCP416015Oil Type:NOT GIVENJob No:JJ SPRAGUE

VOINTO

SAMPLE IN	FORMATION			
Sample Number	-	VCP416015	 	
Sample Date		28 Aug 2023	 	
Machine Hours		14253	 	
Sample Status		ABNORMAL	 	
COOLANT	CONDITION			
рН	Scale 0-14	8.68	 	
Reserve Alkalinity	Scale 0-20		 	
Nitrites	ppm	0	 	
Percentage Glycol	%	<b>43.4</b>	 	
Freezing Point	°C	<b>-19</b>	 	
CONTAMIN	IATION			
Coolant Appearance		🔺 sediment	 	
Coolant Color		Yllow	 	



#### ARNOLD MACHINERY COMPANY

4323 EAST WINSLOW AVENUE PHOENIX, AZ US 85040 Contact: RANDY PRZEKURAT randyp@arnoldmachinery.com T: F: (602)414-1904

### Diagnosis

We recommend drain/flush system, and refill with 50/50 antifreeze water mixture. Sediment present. The carboxylate level of this fluid is acceptable. The glycol level is acceptable. The pH level of this fluid is within the acceptable limits.

 Depot:
 VOLVO6174

 Unique No:
 10634656

 Signed:
 Doug Bogart

 Report Date:
 08 Sep 2023

## **CONSTRUCTION EQUIPMENT**



# GRAPHS

### Iron/Tin/Silver

VOLVO

