



CONSTRUCTION EQUIPMENT

3495BR VOLVO L180F 11639 - TRANSMISSION (AUTO)



Sample No: VCP435031
Oil Type: DEXRON III
Job No: 3495BR



SAMPLE INFORMATION

Sample Number	VCP435031	---	---	---
Sample Date	05 Sep 2023	---	---	---
Machine Hours	14979	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Not Chngd	---	---	---
Sample Status	NORMAL	---	---	---

HIGHWAY EQUIPMENT AND SUPPLY CO
 200 BURKHOLDER DR.
 EPHRATA, PA
 US 17522
 Contact: CHAD HERRON
 chad@hwyequip.com
 T: (717)859-3132
 F: (717)859-2698



OIL CONDITION

Visc @ 40°C	cSt	█ 27.6	---	---	---
-------------	-----	--------	-----	-----	-----



CONTAMINATION

Silicon	ppm	█ 3	---	---	---
Sodium	ppm	█ 2	---	---	---
Potassium	ppm	█ 0	---	---	---

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the fluid. The condition of the fluid is acceptable for the time in service.



WEAR METALS

Iron	ppm	█ 27	---	---	---
Copper	ppm	█ 18	---	---	---
Lead	ppm	█ 0	---	---	---
Tin	ppm	█ 0	---	---	---
Aluminum	ppm	█ 2	---	---	---
Chromium	ppm	█ 0	---	---	---
Molybdenum	ppm	█ 0	---	---	---
Nickel	ppm	█ 0	---	---	---
Titanium	ppm	0	---	---	---
Silver	ppm	█ 0	---	---	---
Manganese	ppm	█ <1	---	---	---
Vanadium	ppm	0	---	---	---



ADDITIVES

Calcium	ppm	█ 125	---	---	---
Magnesium	ppm	█ 9	---	---	---
Zinc	ppm	█ 46	---	---	---
Phosphorus	ppm	█ 202	---	---	---
Barium	ppm	█ 0	---	---	---
Boron	ppm	█ 60	---	---	---

Depot: INSEPH
Unique No: 10635572
Signed: Don Baldrige
Report Date: 10 Sep 2023



CONSTRUCTION EQUIPMENT



VOLVO GRAPHS

