CONSTRUCTION EQUIPMENT SWA353593 USED EQUIP VOLVO EC380EL 310235 - HYDRAULIC

Sample No:VCP410325Oil Type:AW HYDRAULIC OIL ISO 46Job No:SWA353593 USED EQUIP

SAMPLE INFORMATION

VOLVO

Sample Number		VCP410325	 	
Sample Date		05 Sep 2023	 	
Machine Hours		7427	 	
Oil Hours		0	 	
Oil Changed		Not Changd	 	
Sample Status		ABNORMAL	 	
OIL CONDITIO	DN			
Visc @ 40°C	St	52.8	 	
Acid Number (AN)	ng KOH/g	0.48	 	
CONTAMINA	TION			

106936

42029

🔺 4619

10

3

■<1

24/23/19

▲



ALTA EQUIPMENT CO - ORLAND PARK

5000 INDUSTRIAL HWY GARY, IN US 46406 Contact: DAVE ENG DAVE.ENG@ALTG.COM T: (312)350-2560 E:

Diagnosis

We recommend you service the filters on this component. Resample at the next service interval to monitor.All component wear rates are normal. There is a high amount of particulates present in the oil. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

WEAR METALS

Particles >4µm

Particles >6µm

Silicon

Sodium

Potassium

Particles >14µm

ISO 4406:1999 (c)

ppm

ppm

ppm

	יוב ו אבס			
Iron	ppm	15	 	
Copper	ppm	17	 	
Lead	ppm	 <1	 	
Tin	ppm	■<1	 	
Aluminum	ppm	3	 	
Chromium	ppm	6	 	
Molybdenum	ppm	0	 	
Nickel	ppm	0	 	
Titanium	ppm	0	 	
Silver	ppm	0	 	
Manganese	ppm	 <1	 	
Vanadium	ppm	<1	 	

ADDITIVES							
Calcium	ppm	105					
Magnesium	ppm	0					
Zinc	ppm	572					
Phosphorus	ppm	455					
Barium	ppm	0					
Boron	ppm	0					

 Depot:
 VOLVO8885

 Unique No:
 10636245

 Signed:
 Don Baldridge

 Report Date:
 11 Sep 2023

Report Id: VOLVO8885 [WUSCAR] 05945633 (Generated: 09/11/2023 13:41:07) Rev: 1


Contact/Location: DAVE ENG - VOLVO8885

CONSTRUCTION EQUIPMENT



GRAPHS

VOLVO



Contact/Location: DAVE ENG - VOLVO8885