



CONSTRUCTION EQUIPMENT

VOLVO L150H 6972 - COOLANT



Sample No: VCP0007491

Oil Type: NOT GIVEN

Job No:



SAMPLE INFORMATION

Sample Number	VCP0007491	---	---	---
Sample Date	06 Sep 2023	---	---	---
Machine Hours	4999	---	---	---
Sample Status	NORMAL	---	---	---



COOLANT CONDITION

pH	Scale 0-14	■ 7.76	---	---	---
Reserve Alkalinity	Scale 0-20	---	---	---	---
Nitrites	ppm	■ NT	---	---	---
Percentage Glycol	%	■ 45.3	---	---	---
Freezing Point	°C	■ -24	---	---	---



CONTAMINATION

Coolant Appearance	normal	---	---	---
Coolant Color	Yllow	---	---	---



ALTA EQUIPMENT COMPANY

8750 PHILIPS HWY
JACKSONVILLE, FL
US 32256

Contact: TECHNICIAN ACCOUNT
catherine.anastasio@wearcheck.com

T:
F: (904)737-1260

Diagnosis

No corrective action is recommended at this time. The fluid is suitable for further service. There is no indication of any contamination in the coolant. Carboxylate test failed. The glycol level is acceptable. The pH level of this fluid is within the acceptable limits.

Depot: VOLVO0092
Unique No: 10642216
Signed: Jonathan Hester
Report Date: 13 Sep 2023



CONSTRUCTION EQUIPMENT




VOLVO GRAPHS


Iron/Tin/Silver




Reserve Alkalinity



Copper/Aluminum/Lead



Freeze Point



pH



Nitrites

