



CONSTRUCTION EQUIPMENT

VOLVO A45G 353134 - REAR AXLE



Sample No: VCP418614
Oil Type: VOLVO PREMIUM GEAR OIL 85W-140 GL-5
Job No:



VOLVO SAMPLE INFORMATION

Sample Number	VCP418614	---	---	---
Sample Date	01 Sep 2023	---	---	---
Machine Hours	1286	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Changed	---	---	---
Sample Status	ATTENTION	---	---	---

ALTA EQUIPMENT COMPANY
 5151 DR MARTIN LUTHER KING BLVD
 FORT MYERS, FL
 US 33905
 Contact: TODD LARK
 tlark@altaequipfl.com
 T:
 F: (239)481-3302

VOLVO OIL CONDITION

Visc @ 40°C	cSt	▲ 51.0	---	---	---
-------------	-----	--------	-----	-----	-----

VOLVO CONTAMINATION

Silicon	ppm	■ 2	---	---	---
Sodium	ppm	■ 2	---	---	---
Potassium	ppm	■ 2	---	---	---

VOLVO WEAR METALS

Iron	ppm	■ 59	---	---	---
Copper	ppm	■ 2	---	---	---
Lead	ppm	■ 0	---	---	---
Tin	ppm	■ 0	---	---	---
Aluminum	ppm	■ <1	---	---	---
Chromium	ppm	■ <1	---	---	---
Molybdenum	ppm	■ 3	---	---	---
Nickel	ppm	■ 0	---	---	---
Titanium	ppm	0	---	---	---
Silver	ppm	0	---	---	---
Manganese	ppm	■ 3	---	---	---
Vanadium	ppm	<1	---	---	---

VOLVO ADDITIVES

Calcium	ppm	■ 103	---	---	---
Magnesium	ppm	■ 0	---	---	---
Zinc	ppm	▲ 14	---	---	---
Phosphorus	ppm	▲ 2381	---	---	---
Barium	ppm	■ 0	---	---	---
Boron	ppm	▲ 263	---	---	---

Diagnosis
 The oil change at the time of sampling has been noted. Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The oil viscosity is lower than normal. This plus the additive levels indicates the addition of a different brand, or type of oil. Confirm oil type.

Depot: VOLVO0090
Unique No: 10642731
Signed: Don Baldrige
Report Date: 13 Sep 2023



CONSTRUCTION EQUIPMENT



GRAPHS

