

CONSTRUCTION EQUIPMENT VOLVO A40G 352676 - FRONT AXLE



Sample No: VCP412493

Oil Type: VOLVO PREMIUM GEAR OIL 85W-140 GL-5

Job No:

IFORMATION				
PURMATION				
	VCP412493	VCP355426	VCP343195	
	05 Sep 2023			
	4379	2274	991	
	Changed	Changed	Changed	
	ABNORMAL	NORMAL	ATTENTION	
TION				
		m 200	A FO 2	
CSL	201	<u> </u>	50.5	
ATION				
ppm	5	1 3	<u>5</u>	
	<1	- <1	1	
	<u> </u>	<1	<u> </u>	
	_	_	_	
FALC				
AL2				
ppm	164	5 6	■ 238	
ppm	■<1	- <1	1	
ppm	0	0	0	
ppm	0	0	0	
ppm	■<1	5	< 1	
ppm	1	- <1	4	
ppm	7	7	4	
ppm	■ <1	0	1	
ppm	0	<1	0	
ppm	0	0	0	
ppm	6	2	1 2	
ppm	<1	0	<1	
5				
ppm	40	□76	8	
ppm	6	2 3	 <1	
	17	34	7	
ppm	1033	971	<u>2215</u>	
	■0	0	0	
	188	_	232	
	ppm	Changed ABNORMAL	4379 2274 0	4379 2274 991 0 0 0 0 0 0 0 0 0



ALTA EQUIPMENT COMPANY

5151 DR MARTIN LUTHER KING BLVD FORT MYERS, FL US 33905 Contact: TODD LARK tlark@altaequipfl.com

T:

F: (239)481-3302

Diagnosis

The oil change at the time of sampling has been noted. We advise that you inspect for the source(s) of metal. Resample at the next service interval to monitor. High concentration of visible metal present. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:VOLVO0090Unique No:10642732Signed:Don BaldridgeReport Date:13 Sep 2023



CONSTRUCTION EQUIPMENT





