



CONSTRUCTION EQUIPMENT


134065 ALJON 30135 - FRONT RIGHT FINAL DRIVE



Sample No: VCP418734

Oil Type: NOT GIVEN

Job No: 134065



SAMPLE INFORMATION

Sample Number	VCP418734	VCP424564	---	---
Sample Date	25 Aug 2023	09 Jun 2023	---	---
Machine Hours	1823	1392	---	---
Oil Hours	0	0	---	---
Oil Changed	Changed	Changed	---	---
Sample Status	NORMAL	NORMAL	---	---

ROMCO INC

1519 W BELTLINE
CARROLLTON, TX
US 75006

Contact: KEVIN CONNOR
kconnor@romco.com
T: (817)980-4947
F: (214)819-4131



OIL CONDITION

Visc @ 40°C	cSt	320	336	---	---
-------------	-----	------------	-----	-----	-----



CONTAMINATION

Silicon	ppm	2	<1	---	---
Sodium	ppm	<1	0	---	---
Potassium	ppm	2	3	---	---



WEAR METALS

Iron	ppm	137	59	---	---
Copper	ppm	1	1	---	---
Lead	ppm	0	0	---	---
Tin	ppm	0	<1	---	---
Aluminum	ppm	0	2	---	---
Chromium	ppm	1	<1	---	---
Molybdenum	ppm	0	0	---	---
Nickel	ppm	0	0	---	---
Titanium	ppm	0	0	---	---
Silver	ppm	0	0	---	---
Manganese	ppm	1	<1	---	---
Vanadium	ppm	0	0	---	---



ADDITIVES

Calcium	ppm	77	2	---	---
Magnesium	ppm	<1	0	---	---
Zinc	ppm	24	0	---	---
Phosphorus	ppm	1025	545	---	---
Barium	ppm	0	0	---	---
Boron	ppm	195	104	---	---

Diagnosis

Resample at the next service interval to monitor. Please specify the brand, type, and viscosity of the oil on your next sample. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: VOLVO0015
Unique No: 10643530
Signed: Wes Davis
Report Date: 13 Sep 2023



CONSTRUCTION EQUIPMENT



VOLVO GRAPHS

