



# CONSTRUCTION EQUIPMENT

SWA355023-2 VOLVO DD140C 290076 - REAR RIGHT PLANETARY



**Sample No:** VCP389687  
**Oil Type:** NOT GIVEN  
**Job No:** SWA355023-2



## SAMPLE INFORMATION

Sample Number	VCP389687	---	---	---
Sample Date	06 Sep 2023	---	---	---
Machine Hours	847	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Not Chngd	---	---	---
Sample Status	NORMAL	---	---	---

### ALTA EQUIPMENT

5985 COURT STREET ROAD  
SYRACUSE, NY  
US 13206  
Contact: JIM STRIGLE  
JIM.STRIGLE@ALTG.COM  
T: (315)437-2611  
F: (315)434-9471



## OIL CONDITION

Visc @ 40°C	cSt	█ 222	---	---	---
-------------	-----	-------	-----	-----	-----



## CONTAMINATION

Silicon	ppm	█ 25	---	---	---
Sodium	ppm	█ 0	---	---	---
Potassium	ppm	█ <1	---	---	---



## WEAR METALS

Iron	ppm	█ 0	---	---	---
Copper	ppm	█ 0	---	---	---
Lead	ppm	█ 0	---	---	---
Tin	ppm	█ 0	---	---	---
Aluminum	ppm	█ 0	---	---	---
Chromium	ppm	█ 0	---	---	---
Molybdenum	ppm	0	---	---	---
Nickel	ppm	█ 0	---	---	---
Titanium	ppm	0	---	---	---
Silver	ppm	0	---	---	---
Manganese	ppm	<1	---	---	---
Vanadium	ppm	0	---	---	---



## ADDITIVES

Calcium	ppm	2	---	---	---
Magnesium	ppm	2	---	---	---
Zinc	ppm	0	---	---	---
Phosphorus	ppm	463	---	---	---
Barium	ppm	0	---	---	---
Boron	ppm	0	---	---	---

### Diagnosis

Resample at the next service interval to monitor. Please specify the brand, type, and viscosity of the oil on your next sample. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

**Depot:** VOLV00142  
**Unique No:** 10643537  
**Signed:** Sean Felton  
**Report Date:** 13 Sep 2023



# CONSTRUCTION EQUIPMENT



## VOLVO GRAPHS

