



CONSTRUCTION EQUIPMENT

VOLVO A60H 350190 - REAR RIGHT FINAL DRIVE



Sample No: VCP433936

Oil Type: NOT GIVEN

Job No:



SAMPLE INFORMATION

Sample Number	VCP433936	VCP383073	VCP371253	VCP389238
Sample Date	05 Sep 2023	05 May 2023	19 Jan 2023	28 Sep 2022
Machine Hours	2618	2128	1651	1183
Oil Hours	0	0	0	0
Oil Changed	Not Chngd	Not Chngd	Not Chngd	N/A
Sample Status	NORMAL	NORMAL	NORMAL	NORMAL

SAIIA CONSTRUCTION LLC

4400 LEWISBURG RD

BIRMINGHAM, AL

US 35207

Contact: STEPHANI BRITTON

sbritton@saiia.com;doug.bogart@wearcheck.com

T: (205)943-2268

F: (205)943-2269



OIL CONDITION

Visc @ 40°C	cSt	51.1	50.5	49.4	49.8
-------------	-----	-------------	------	------	------



CONTAMINATION

Silicon	ppm	3	2	2	3
Sodium	ppm	3	3	3	3
Potassium	ppm	3	3	2	0



WEAR METALS

Iron	ppm	105	121	70	75
Copper	ppm	<1	<1	<1	1
Lead	ppm	0	0	0	0
Tin	ppm	<1	<1	0	0
Aluminum	ppm	<1	0	<1	0
Chromium	ppm	2	2	1	<1
Molybdenum	ppm	2	3	2	3
Nickel	ppm	<1	<1	0	<1
Titanium	ppm	0	0	0	<1
Silver	ppm	<1	0	0	<1
Manganese	ppm	6	6	4	5
Vanadium	ppm	0	0	0	2



ADDITIVES

Calcium	ppm	349	335	312	328
Magnesium	ppm	3	2	1	0
Zinc	ppm	149	147	144	131
Phosphorus	ppm	2323	2399	2192	2487
Barium	ppm	0	0	<1	0
Boron	ppm	300	280	280	302

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: SAIBIR

Unique No: 10643563

Signed: Sean Felton

Report Date: 13 Sep 2023



CONSTRUCTION EQUIPMENT



GRAPHS

