



CONSTRUCTION EQUIPMENT

134247 VOLVO L260H 1362 - TRANSMISSION (AUTO)



Sample No: VCP435419
Oil Type: DEXRON III
Job No: 134247



SAMPLE INFORMATION

Sample Number	VCP435419	VCP408803	---	---
Sample Date	01 Sep 2023	24 Jul 2023	---	---
Machine Hours	1072	595	---	---
Oil Hours	0	0	---	---
Oil Changed	Not Chngd	Not Chngd	---	---
Sample Status	NORMAL	NORMAL	---	---

LATTIMORE MATERIALS/HOLCIM - ROSSER - LAFARGE
 14242 S SH-34
 SCURRY, TX
 US 75158
 Contact: WALLACE WARREN
 wallace.warren@lafargeholcim.com
 T:
 F:



OIL CONDITION

Visc @ 40°C	cSt	27.6	27.8	---	---
-------------	-----	-------------	------	-----	-----



CONTAMINATION

Silicon	ppm	9	9	---	---
Sodium	ppm	5	2	---	---
Potassium	ppm	<1	1	---	---

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the fluid. The condition of the fluid is acceptable for the time in service.



WEAR METALS

Iron	ppm	130	95	---	---
Copper	ppm	6	6	---	---
Lead	ppm	0	<1	---	---
Tin	ppm	0	0	---	---
Aluminum	ppm	2	2	---	---
Chromium	ppm	1	<1	---	---
Molybdenum	ppm	0	<1	---	---
Nickel	ppm	0	<1	---	---
Titanium	ppm	0	0	---	---
Silver	ppm	0	0	---	---
Manganese	ppm	6	5	---	---
Vanadium	ppm	0	0	---	---



ADDITIVES

Calcium	ppm	74	75	---	---
Magnesium	ppm	2	2	---	---
Zinc	ppm	10	14	---	---
Phosphorus	ppm	186	180	---	---
Barium	ppm	2	0	---	---
Boron	ppm	76	98	---	---

Depot: LATSCU
Unique No: 10643575
Signed: Wes Davis
Report Date: 13 Sep 2023



CONSTRUCTION EQUIPMENT



VOLVO GRAPHS

