



# CONSTRUCTION EQUIPMENT

19269 VOLVO A45G 352805 - TRANSMISSION (AUTO)



Sample No: VCP408334

Oil Type: DEXRON III

Job No: 19269



## SAMPLE INFORMATION

Sample Number	VCP408334	---	---	---
Sample Date	19 Jul 2023	---	---	---
Machine Hours	8125	---	---	---
Oil Hours	0	---	---	---
Oil Changed	N/A	---	---	---
Sample Status	NORMAL	---	---	---

### GLOVER CONSTRUCTION CO. INC.

4493 US HWY 301 N

PLEASANT HILL, NC

US 27866

Contact: BRENDA GAY

bgay@gloverconstruction.com

T:

F: (252)536-5078



## OIL CONDITION

Visc @ 40°C	cSt	█ 31.0	---	---	---
-------------	-----	--------	-----	-----	-----



## CONTAMINATION

Silicon	ppm	█ 4	---	---	---
Sodium	ppm	█ 1	---	---	---
Potassium	ppm	█ 4	---	---	---



## WEAR METALS

Iron	ppm	█ 6	---	---	---
Copper	ppm	█ 4	---	---	---
Lead	ppm	█ 0	---	---	---
Tin	ppm	█ <1	---	---	---
Aluminum	ppm	█ <1	---	---	---
Chromium	ppm	█ 0	---	---	---
Molybdenum	ppm	█ 0	---	---	---
Nickel	ppm	█ <1	---	---	---
Titanium	ppm	█ 0	---	---	---
Silver	ppm	█ 0	---	---	---
Manganese	ppm	█ <1	---	---	---
Vanadium	ppm	█ 0	---	---	---



## ADDITIVES

Calcium	ppm	█ 77	---	---	---
Magnesium	ppm	█ 4	---	---	---
Zinc	ppm	█ 2	---	---	---
Phosphorus	ppm	█ 264	---	---	---
Barium	ppm	█ 0	---	---	---
Boron	ppm	█ 132	---	---	---

## Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the fluid. The condition of the fluid is acceptable for the time in service.

Depot: GLOPLE

Unique No: 10644320

Signed: Don Baldrige

Report Date: 14 Sep 2023



# CONSTRUCTION EQUIPMENT



## GRAPHS

