

CONSTRUCTION EQUIPMENT

595813 DIPRO SENNEBOGAN 835 830.0.2853 - FRONT LEFT FINA

Sample No: VCP413262

Oil Type: VOLVO PREMIUM GEAR OIL 80W-90 GL-5

Job No: 595813 DIPRO

VOLVO					
SAMPLE	INFORMATION	l			
Sample Number	-	VCP413262	VCP426792	VCP386899	
Sample Date		05 Sep 2023	29 Mar 2023	30 Aug 2022	
Machine Hours		4123	3387	1894	
Oil Hours		1000	1000	1000	
Oil Changed		Changed	Changed	Changed	
Sample Status		NORMAL	NORMAL	NORMAL	
OIL CON	DITION				
Visc @ 40°C	cSt	141	□ 144	□ 162	
VOLVO	ALLIA TION				
LUNTAN	MINATION				
Silicon	ppm	■ 3	4	2	
Sodium	ppm	■ 3	- <1	1 3	
Potassium	ppm	■3	1	0	
WEAR N	METALS				
Iron	ppm	■59	7 5	227	
Copper	ppm	■8	4	4 5	
Lead	ppm	■ <1	□0	0	
Tin	ppm	■ <1	0	0	
Aluminum	ppm	0	< 1	2	
Chromium	ppm	■ <1	0	- <1	
Molybdenum	ppm	■<1	0		
Nickel	ppm	■ 0	0	0	
Titanium	ppm	0	0	0	
Silver	ppm	0	0	0	
Manganese	ppm	■2	2	7	
Vanadium	ppm	0	0	0	
ADDITIV	IES				
Calcium	ppm	5	1	1 4	
Magnesium	ppm	2	0	□ 0	
Zinc	ppm	7	□0	4 3	
Phosphorus	ppm	1036	■2352	■ 1537	
Barium	ppm	0	0	1 01	
Boron	ppm	49	186	6 7	



ALTA EQUIPMENT COMPANY - METRO WEST 56195 PONTIAC TRAIL NEW HUDSON, MI US 48165 Contact: PAUL CONZ paul.conz@altg.com T: (313)348-8861 F: (248)356-2029

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:VOLVO2990Unique No:10645578Signed:Don BaldridgeReport Date:15 Sep 2023



CONSTRUCTION EQUIPMENT





