

## **CONSTRUCTION EQUIPMENT**

4298DR KINSLEY CONST VOLVO A45G 352858 - TRANSMISSION

Sample No: VCP399661

Oil Type: VOLVO AUTOMATIC TRANSMISSION FLUID AT102

**Job No:** 4298DR KINSLEY CONST

VOLVO SAMPLE	INFORMATION	N .			
	INI OMPATIO				<u>.</u>
Sample Number		VCP399661			
Sample Date		06 Sep 2023			
Machine Hours		2577			
Oil Hours		0			
Oil Changed		Not Changd			
Sample Status		ABNORMAL			
VOLVO					
OIL CONDITION					
Visc @ 40°C	cSt	<b>□</b> 28.7			
VOLVO					
CONTAN	IINATION				
Silicon	ppm	<b>4</b>			
Sodium	ppm	<b>■</b> 3			
Potassium	ppm	<b>2</b>			
WEAR M	IFTALS				
Iron	ppm	<b>8</b>			
Copper	ppm	<b>5</b>			
Lead		<b>■</b> <1			
Tin	ppm	■<1			
Aluminum	ppm	<b>■</b> <1			
	ppm	_			
Chromium	ppm	<b>■</b> <1			
Molybdenum	ppm	2			
Nickel	ppm	<b></b>			
Titanium	ppm	0			
Silver	ppm	■0			
Manganese	ppm	<b></b>			
Vanadium	ppm	0			
VOLVO					
<b>ADDITIV</b>	ES				
Calcium	ppm	<b>143</b>			
Magnesium	ppm	<b>18</b>			
Zinc	ppm	■32			
Phosphorus	ppm	<b>190</b>			
Barium	ppm	■0			
Boron	ppm	<b>71</b>			
	PP				



#### **HIGHWAY EQUIPMENT & SUPPLY CO**

PO BOX 127 DRUMS, PA US 18222 Contact: JUSTIN BLOSS justin@hwyequip.com T: (570)788-1127 F: (570)708-2933

### Diagnosis

No corrective action is recommended at this time. Resample at the next service interval to monitor.All component wear rates are normal. Moderate concentration of visible dirt/debris present in the fluid. The condition of the fluid is acceptable for the time in service.

Depot:VOLVO0022Unique No:10645658Signed:Jonathan HesterReport Date:15 Sep 2023



# **CONSTRUCTION EQUIPMENT**





