



CONSTRUCTION EQUIPMENT

SWO-065604 VOLVO A60H 350187 - FRONT LEFT FINAL DRIVE



Sample No: VCP433456
Oil Type: NOT GIVEN
Job No: SWO-065604



SAMPLE INFORMATION

Sample Number	VCP433456	VCP402251	VCP388255	VCP357783
Sample Date	06 Sep 2023	28 Feb 2023	14 Oct 2022	08 Aug 2022
Machine Hours	2021	1556	1098	537
Oil Hours	0	0	0	0
Oil Changed	Not Chngd	Not Chngd	Not Chngd	Not Chngd
Sample Status	NORMAL	NORMAL	NORMAL	ABNORMAL

SAIIA CONSTRUCTION LLC

4400 LEWISBURG RD
 BIRMINGHAM, AL
 US 35207

Contact: STEPHANI BRITTON
 sbritton@saiia.com;doug.bogart@wearcheck.com
 T: (205)943-2268
 F: (205)943-2269



OIL CONDITION

Visc @ 40°C	cSt	49.2	49.7	51.5	50.3
-------------	-----	-------------	------	------	------



CONTAMINATION

Silicon	ppm	2	2	2	3
Sodium	ppm	2	2	1	2
Potassium	ppm	3	0	0	2

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.



WEAR METALS

Iron	ppm	57	97	87	78
Copper	ppm	<1	<1	<1	<1
Lead	ppm	0	0	<1	0
Tin	ppm	0	0	0	<1
Aluminum	ppm	0	<1	0	1
Chromium	ppm	<1	2	<1	2
Molybdenum	ppm	<1	2	2	2
Nickel	ppm	0	<1	<1	<1
Titanium	ppm	0	<1	0	0
Silver	ppm	0	0	0	<1
Manganese	ppm	3	7	7	6
Vanadium	ppm	0	0	<1	0



ADDITIVES

Calcium	ppm	346	336	326	347
Magnesium	ppm	1	4	0	1
Zinc	ppm	159	140	142	164
Phosphorus	ppm	2442	2097	2133	2384
Barium	ppm	0	0	0	2
Boron	ppm	285	277	254	299

Depot: SAIBIR
Unique No: 10646457
Signed: Angela Borella
Report Date: 18 Sep 2023



CONSTRUCTION EQUIPMENT



GRAPHS

