

Sample No: VCP384973
Oil Type: VOLVO WB 102

Job No: 12495 PRIORTIY WASTE

CAMPI	E INFORMATION			
Sample Number		VCP384973	VCP363970	
Sample Date Machine Hours		02 Sep 2023 4047	26 Aug 2022 997	
		4047		
Oil Hours			0	
Oil Changed		Changed	Changed	
Sample Status		NORMAL	NORMAL	
VOLVO				
OIL CON	DITION			
Visc @ 40°C	cSt	41.9	1 40.4	
VOLVO	AIN A TION			
LUNIAN	MINATION			
Silicon	ppm	22	1 9	
Sodium	ppm	4	9	
Potassium	ppm	0	2	
WEAR	AETALS			
WEAR	JE I WEZ	·		
Iron	ppm	104	4 7	
Copper	ppm	■1	<u></u> <1	
Lead	ppm	■ <1	- <1	
Tin	ppm	■ <1	0	
Aluminum	ppm	■3	2	
Chromium	ppm	2	3	
Molybdenum	ppm	4	1 3	
Nickel	ppm	■<1	0	
Titanium	ppm	<1	<1	
Silver	ppm	0	0	
Manganese	ppm	6	■8	
Vanadium	ppm	<1	0	
ADDITIV	/FS			
Calcium	ppm	4063	■3931	
Magnesium	ppm	13	10	
Zinc		■ 1594	■ 1632	
Phosphorus	ppm	1312	1308	
•	ppm	_		
Barium	ppm	0	<1	
Boron	ppm	150	143	



536 - ASCENDUM MACHINERY INC - CHATTANOOGA 7829 LEE HWY CHATTANOOGA, TN US 37421 Contact: WILLIAM WALKER william.walker@ascendummachinery.com T:

F: (423)308-7959

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:VOLVO0117Unique No:10646918Signed:Don BaldridgeReport Date:19 Sep 2023



CONSTRUCTION EQUIPMENT





