

CONSTRUCTION EQUIPMENT X58455 VOLVO EC300EL 316607 - SWING DRIVE



Sample No: VCP413369
Oil Type: NOT GIVEN
Job No: X58455

VOLVO				
SAMPLE	E INFORMATIO	N		
Sample Number		VCP413369	 	
Sample Date		08 Sep 2023	 	
Machine Hours		1462	 	
Oil Hours		0	 	
Oil Changed		N/A	 	
Sample Status		ABNORMAL	 	
OIT CON	DITION			
Visc @ 40°C	cSt	184	 	
CUNTAR	MINATION			
_		-40		
Silicon	ppm	18	 	
Sodium	ppm	2	 	
Potassium	ppm	■ <1	 	
VOLVO				
WEAR N	METALS			
Iron	ppm	<u> </u>	 	
Copper	ppm	■ 36	 	
Lead	ppm	0	 	
Tin	ppm	-<1	 	
Aluminum	ppm	4	 	
Chromium	ppm	<u> </u>	 	
Molybdenum	ppm	0	 	
Nickel	ppm	2	 	
Titanium	ppm	0	 	
Silver	ppm	0	 	
Manganese	ppm	16	 	
Vanadium	ppm	0	 	
ADDITIV	VES			
Calcium	ppm	11	 	
Magnesium	ppm	4	 	
Zinc	ppm	33	 	
Phosphorus	ppm	362	 	
Barium	ppm	4	 	
Boron	ppm	0	 	
DOTOIT	ррпп	V		



SCOTT EQUIPMENT COMPANY LLC - Saint Rose
PO BOX 997
SAINT ROSE, LA
US 70087
Contact: DENISE CORVERS
dcorvers@scottcompanies.com
T: (504)461-0961
F: (504)461-0970

Diagnosis

No corrective action is recommended at this time. Resample at the next service interval to monitor. Gear wear is indicated. All other component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:SCOSAIUnique No:10647719Signed:Don BaldridgeReport Date:19 Sep 2023



CONSTRUCTION EQUIPMENT





