CONSTRUCTION EQUIPMENT 19481 KOPPERS VOLVO L120H 632917 - COOLANT



 Sample No:
 VCP434902

 Oil Type:
 VOLVO COOLANT VCS (YELLOW)

 Job No:
 19481 KOPPERS

VOLVO

Coolant Color

SAMPLE II	NFORMATION			
Sample Number	-	VCP434902	 	
Sample Date		06 Sep 2023	 	
Machine Hours		4106	 	
Sample Status		NORMAL	 	
COOLANT	CONDITION			
рН	Scale 0-14	7.40	 	
Reserve Alkalinity	Scale 0-20		 	
Nitrites	ppm	0	 	
Percentage Glycol	%	48.5	 	
Freezing Point	°C	-31	 	
CONTAMI	NATION			
Coolant Appearance	-	normal	 	

Yllow



117 - ASCENDUM MACHINERY INC - GREENVILLE 2002 N GREENE ST GREENVILLE, NC US 27834 Contact: BRANDON JENKINS BRANDON JENKINS@ASCENDUMMACHINERY.COM T: F: (704)494-8197

Diagnosis

No corrective action is recommended at this time. The fluid is suitable for further service. There is no indication of any contamination in the coolant. Carboxylate test failed. The glycol level is acceptable. The pH level of this fluid is within the acceptable limits.

 Depot:
 VOLVO8769

 Unique No:
 10647842

 Signed:
 Doug Bogart

 Report Date:
 20 Sep 2023


CONSTRUCTION EQUIPMENT



GRAPHS

Iron/Tin/Silver

VOLVO



Sep6/23.

Sep6/23

Sep6/23