



CONSTRUCTION EQUIPMENT

19473 VOLVO L90H 623682 - COOLANT



Sample No: VCP421692
Oil Type: VOLVO COOLANT VCS (YELLOW)
Job No: 19473



SAMPLE INFORMATION

Sample Number	VCP421692	---	---	---
Sample Date	05 Sep 2023	---	---	---
Machine Hours	12074	---	---	---
Sample Status	NORMAL	---	---	---



IAA - INSURANCE AUTO AUCTIONS - CLAYTON
 60 SADISCO RD
 CLAYTON, NC
 US 27520
 Contact: Service Manager



COOLANT CONDITION

pH	Scale 0-14	7.98	---	---	---
Reserve Alkalinity	Scale 0-20	---	---	---	---
Nitrites	ppm	0	---	---	---
Percentage Glycol	%	58.9	---	---	---
Freezing Point	°C	-54	---	---	---

T:
F:



CONTAMINATION

Coolant Appearance	normal	---	---	---
Coolant Color	Yllow	---	---	---

Diagnosis

The fluid is suitable for further service. There is no indication of any contamination in the coolant. The carboxylate level of this fluid is acceptable. The glycol level is acceptable. The pH level of this fluid is within the acceptable limits.

Depot: INSCLA
Unique No: 10647843
Signed: Doug Bogart
Report Date: 20 Sep 2023



CONSTRUCTION EQUIPMENT




GRAPHS


Iron/Tin/Silver




Reserve Alkalinity




Copper/Aluminum/Lead



Freeze Point



pH



Nitrites

