



CONSTRUCTION EQUIPMENT

PUMP 2 - PUMP



Sample No: VCP326065
Oil Type: NOT GIVEN
Job No:



SAMPLE INFORMATION

Sample Number	VCP326065	VCP386939	---	---
Sample Date	05 Sep 2023	27 Aug 2023	---	---
Machine Hours	0	0	---	---
Oil Hours	0	0	---	---
Oil Changed	N/A	N/A	---	---
Sample Status	NORMAL	NORMAL	---	---

ALTA EQUIPMENT/FLAGLER CONSTRUCTION EQUIPMENT LLC
 8418 PALM RIVER ROAD
 TAMPA, FL
 US 33619
 Contact: KENNY HANEY
 khaney@flaglerce.com
 T: (813)630-0077
 F: (813)630-2233



OIL CONDITION

Visc @ 40°C	cSt	148	147	---	---
-------------	-----	------------	-----	-----	-----



CONTAMINATION

Silicon	ppm	8	7	---	---
Sodium	ppm	0	<1	---	---
Potassium	ppm	2	0	---	---

Diagnosis

Resample at the next service interval to monitor. Please specify the brand, type, and viscosity of the oil on your next sample. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.



WEAR METALS

Iron	ppm	4	4	---	---
Copper	ppm	0	0	---	---
Lead	ppm	0	0	---	---
Tin	ppm	0	0	---	---
Aluminum	ppm	<1	0	---	---
Chromium	ppm	0	0	---	---
Molybdenum	ppm	0	<1	---	---
Nickel	ppm	0	0	---	---
Titanium	ppm	0	0	---	---
Silver	ppm	0	0	---	---
Manganese	ppm	0	<1	---	---
Vanadium	ppm	0	0	---	---



ADDITIVES

Calcium	ppm	2	2	---	---
Magnesium	ppm	0	0	---	---
Zinc	ppm	0	0	---	---
Phosphorus	ppm	96	99	---	---
Barium	ppm	0	0	---	---
Boron	ppm	0	0	---	---

Depot: VOLVO0093
Unique No: 10648982
Signed: Wes Davis
Report Date: 18 Sep 2023



CONSTRUCTION EQUIPMENT



GRAPHS

