



CONSTRUCTION EQUIPMENT

SW-1023869 SUNROC VOLVO A40G 340694 - BOGIE/CENTER AXLE



Sample No: VCP419390
Oil Type: NOT GIVEN
Job No: SW-1023869 SUNROC



SAMPLE INFORMATION

Sample Number	VCP419390	---	---	---
Sample Date	11 Sep 2023	---	---	---
Machine Hours	9476	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Not Chngd	---	---	---
Sample Status	NORMAL	---	---	---

ARNOLD MACHINERY COMPANY
2975 WEST 2100 SOUTH
SALT LAKE CITY, UT
US 84119
Contact: KEVIN ARNONE
karnone@arnoldmachinery.com
T: (801)972-4000
F: (801)975-9434



OIL CONDITION

Visc @ 40°C	cSt	█ 187	---	---	---
-------------	-----	-------	-----	-----	-----



CONTAMINATION

Silicon	ppm	█ 19	---	---	---
Sodium	ppm	█ 0	---	---	---
Potassium	ppm	█ 0	---	---	---

Diagnosis

Resample at the next service interval to monitor. Please specify the brand, type, and viscosity of the oil on your next sample. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.



WEAR METALS

Iron	ppm	█ 419	---	---	---
Copper	ppm	█ 8	---	---	---
Lead	ppm	█ <1	---	---	---
Tin	ppm	█ <1	---	---	---
Aluminum	ppm	█ 7	---	---	---
Chromium	ppm	█ 4	---	---	---
Molybdenum	ppm	3	---	---	---
Nickel	ppm	█ 3	---	---	---
Titanium	ppm	<1	---	---	---
Silver	ppm	0	---	---	---
Manganese	ppm	8	---	---	---
Vanadium	ppm	0	---	---	---



ADDITIVES

Calcium	ppm	3223	---	---	---
Magnesium	ppm	15	---	---	---
Zinc	ppm	1031	---	---	---
Phosphorus	ppm	922	---	---	---
Barium	ppm	0	---	---	---
Boron	ppm	22	---	---	---

Depot: VOLVO8770
Unique No: 10649021
Signed: Angela Borella
Report Date: 19 Sep 2023



CONSTRUCTION EQUIPMENT



GRAPHS

