

CONSTRUCTION EQUIPMENT VOLVO L70H 624288 - DIESEL ENGINE



Sample No: VCP425009

Oil Type:

VOLVO ULTRA DIESEL ENGINE OIL 15W40 VDS-3

Job No:

Vanadium

Calcium

Zinc

Barium

Boron

Magnesium

Phosphorus

ppm

ppm

ppm

ppm

ppm

ppm

ppm

ADDITIVES

SAMPLE	INFORMATION					
Sample Number		VCP425009	VCP355080			2 - 4 200 A mb-664
Sample Date		16 Aug 2023	20 Jun 2022			ALTA EQUIPMENT/FLAGLER
Machine Hours		2287	925			8418 PALM RIVER
Oil Hours		0	300			TAMPA, FL
Oil Changed		Changed	Changed			US 33619
Sample Status		ATTENTION	NORMAL			Contact: KENNY H
						khaney@flaglerce
OIL CONDITION						T: (813)630-0077 F: (813)630-2233
Visc @ 100°C	cSt	11.8	13.3			1. (013)030 2233
Base Number (BN)) mg KOH/g	7.1	9.9			
Oxidation (PA)	%	47	59			Diagnosis
						Oil and filter char
VOLVO						sampling has bee
						at the next service
Soot %	%	0.3	0.2			monitor.All comp
Nitration (PA)	%	53	54			are normal. Fuel o There is no indica
Sulfation (PA)	%	47	53			contamination in
Glycol	%	NEG	NEG			viscosity is lower
Fuel	%	0.3	<1.0			BN result indicate
Silicon	ppm	5	4			suitable alkalinity
Sodium	ppm	2	 <1			Confirm oil type.
Potassium	ppm	2	2			
VOLVO						
VEAR MI	ETALS					
Iron	ppm	1 4	8			
Copper	ppm	2	<1			
Lead	ppm	0	0			
Tin	ppm	□ <1	<1			
Aluminum	ppm	6	4			
Chromium	ppm	1	1			
Molybdenum	ppm	52	61			
Nickel	ppm	0	0			
Titanium	ppm	<1	0			
Silver	ppm	0	0			
Manganese	ppm	 <1	< 1			
-			0			

1726

393

1242

1028

0

6



A EQUIPMENT/FLAGLER CONSTRUCTION EQUIPMENT LLC 18 PALM RIVER ROAD MPA, FL 33619 ontact: KENNY HANEY aney@flaglerce.com (813)630-0077

iagnosis

il and filter change at the time of ampling has been noted. Resample the next service interval to nonitor.All component wear rates re normal. Fuel content negligible. here is no indication of any ontamination in the oil. The oil scosity is lower than normal. The N result indicates that there is itable alkalinity remaining in the oil. onfirm oil type.

Depot: VOLVO0093 Unique No: Signed: Report Date:

10649662 Don Baldridge 20 Sep 2023

<1

1692

378

1232

969

0 🔲

|| <1

Contact/Location: KENNY HANEY - VOLVO0093

CONSTRUCTION EQUIPMENT



GRAPHS

VOLVO

