



CONSTRUCTION EQUIPMENT

13418 INASHCO VOLVO L150H 6177 - REAR AXLE



Sample No: VCP415411
Oil Type: VOLVO SUPER GEAR OIL 75W-80-GO102
Job No: 13418 INASHCO



McClung-Logan Virginia LLC- RICHMOND
 1345 MOUNTAIN ROAD
 GLEN ALLEN, VA
 US 23060
 Contact: KYLE RATLIFFE
 KRATLIFFE@MCCLUNG-LOGAN.COM
 T:
 F: (804)266-1611



SAMPLE INFORMATION

Sample Number	VCP415411	---	---	---
Sample Date	12 Sep 2023	---	---	---
Machine Hours	8000	---	---	---
Oil Hours	2000	---	---	---
Oil Changed	Changed	---	---	---
Sample Status	NORMAL	---	---	---



OIL CONDITION

Visc @ 40°C	cSt	█ 41.8	---	---	---
-------------	-----	--------	-----	-----	-----



CONTAMINATION

Silicon	ppm	█ 9	---	---	---
Sodium	ppm	█ 7	---	---	---
Potassium	ppm	█ <1	---	---	---



WEAR METALS

Iron	ppm	█ 50	---	---	---
Copper	ppm	█ 13	---	---	---
Lead	ppm	█ 0	---	---	---
Tin	ppm	█ <1	---	---	---
Aluminum	ppm	█ <1	---	---	---
Chromium	ppm	█ <1	---	---	---
Molybdenum	ppm	█ 2	---	---	---
Nickel	ppm	█ 0	---	---	---
Titanium	ppm	<1	---	---	---
Silver	ppm	0	---	---	---
Manganese	ppm	█ 1	---	---	---
Vanadium	ppm	<1	---	---	---



ADDITIVES

Calcium	ppm	█ 3519	---	---	---
Magnesium	ppm	█ 4	---	---	---
Zinc	ppm	█ 1523	---	---	---
Phosphorus	ppm	█ 1244	---	---	---
Barium	ppm	█ 0	---	---	---
Boron	ppm	█ 113	---	---	---

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: VOLVO8882
Unique No: 10655590
Signed: Jonathan Hester
Report Date: 20 Sep 2023



CONSTRUCTION EQUIPMENT



GRAPHS

