



CONSTRUCTION EQUIPMENT

SWA350844-10 VOLVO EC300E 314225 - COOLANT



Sample No: VCP405620
Oil Type: VOLVO COOLANT VCS (YELLOW)
Job No: SWA350844-10



SAMPLE INFORMATION

Sample Number	VCP405620	VCP407002	VCP374139	VCP343260
Sample Date	07 Sep 2023	09 Jun 2023	10 Jun 2022	11 Feb 2022
Machine Hours	4869	4288	2242	1600
Sample Status	NORMAL	NORMAL	NORMAL	NORMAL

DENALI WE CARE

400 TORNE RD
HILLBURN, NY
US 10931
Contact: Service Manager



COOLANT CONDITION

pH	Scale 0-14	7.43	7.55	7.79	7.88
Reserve Alkalinity	Scale 0-20	---	---	---	---
Nitrites	ppm	0	0	0	NT
Percentage Glycol	%	58.0	55.8	47.7	47.2
Freezing Point	°C	-54	-47	-28	-28

T:
F:

Diagnosis

The fluid is suitable for further service. There is no indication of any contamination in the coolant. The carboxylate level of this fluid is acceptable. The glycol level is acceptable. The pH level of this fluid is within the acceptable limits.



CONTAMINATION

Coolant Appearance	normal	normal	normal	normal
Coolant Color	Yllow	Yllow	Yllow	Yllow

Depot: DENHIL
Unique No: 10655713
Signed: Doug Bogart
Report Date: 20 Sep 2023




CONSTRUCTION EQUIPMENT




VOLVO GRAPHS


Iron/Tin/Silver




Reserve Alkalinity




Copper/Aluminum/Lead



Freeze Point



pH



Nitrites

