



CONSTRUCTION EQUIPMENT

VOLVO EC350EL 314416 - COOLANT



Sample No: VCP441899
Oil Type: VOLVO COOLANT VCS (YELLOW)
Job No:



SAMPLE INFORMATION

Sample Number	VCP441899	---	---	---
Sample Date	14 Sep 2023	---	---	---
Machine Hours	353597	---	---	---
Sample Status	NORMAL	---	---	---

CALLANAN
 RT 32 677 FLATBUSH RD
 EAST KINGSTON, NY
 US 12401
 Contact:



COOLANT CONDITION

pH	Scale 0-14	█ 7.38	---	---	---
Reserve Alkalinity	Scale 0-20	---	---	---	---
Nitrites	ppm	█ 0	---	---	---
Percentage Glycol	%	█ 48.3	---	---	---
Freezing Point	°C	█ -31	---	---	---

T:
F:



CONTAMINATION

Coolant Appearance	normal	---	---	---
Coolant Color	Yllow	---	---	---

Diagnosis

No corrective action is recommended at this time. The fluid is suitable for further service. There is no indication of any contamination in the coolant. Carboxylate test failed. The glycol level is acceptable. The pH level of this fluid is within the acceptable limits.

Depot: CALEAS
Unique No: 10655714
Signed: Doug Bogart
Report Date: 20 Sep 2023



CONSTRUCTION EQUIPMENT




GRAPHS


Iron/Tin/Silver




Reserve Alkalinity



Copper/Aluminum/Lead



Freeze Point



pH



Nitrites

