



CONSTRUCTION EQUIPMENT

SWA329757-20 VOLVO L220H 2823 - COOLANT



Sample No: VCP407092
Oil Type: VOLVO COOLANT VCS (YELLOW)
Job No: SWA329757-20



SAMPLE INFORMATION

Sample Number	VCP407092	VCP364975	VCP316707	VCP306378
Sample Date	09 Sep 2023	16 Sep 2022	02 Feb 2022	05 Aug 2021
Machine Hours	7460	7531	6156	5330
Sample Status	NORMAL	NORMAL	NORMAL	NORMAL



CALLANAN
 RT 32 677 FLATBUSH RD
 EAST KINGSTON, NY
 US 12401
 Contact:



COOLANT CONDITION

pH	Scale 0-14	6.96	6.95	6.97	7.06
Reserve Alkalinity	Scale 0-20	---	---	---	---
Nitrites	ppm	NT	NT	NT	0
Percentage Glycol	%	47.4	46.5	46.4	46
Freezing Point	°C	-28	-26	-26	-29

T:
F:



CONTAMINATION

Coolant Appearance	normal	normal	normal	normal
Coolant Color	Yllow	Yllow	Yllow	Yllow

Diagnosis

No corrective action is recommended at this time. The fluid is suitable for further service. There is no indication of any contamination in the coolant. Carboxylate test failed. The glycol level is acceptable. The pH level of this fluid is within the acceptable limits.

Depot: CALEAS
Unique No: 10655717
Signed: Doug Bogart
Report Date: 20 Sep 2023




CONSTRUCTION EQUIPMENT




VOLVO GRAPHS


Iron/Tin/Silver




Reserve Alkalinity




Copper/Aluminum/Lead



Freeze Point



pH



Nitrites

