



CONSTRUCTION EQUIPMENT

23964 VOLVO L70H 623763 - TRANSMISSION (AUTO)



Sample No: VCP435177
Oil Type: VOLVO AUTOMATIC TRANSMISSION FLUID AT102
Job No: 23964



218 - ASCENDUM MACHINERY INC - N. CHARLESTON
 7235 CROSS COUNTRY RD.
 NORTH CHARLESTON, SC
 US 29418
 Contact: MATT MITCHAM
 matt.mitcham@ascendummachinery.com
 T:
 F: (843)414-1129



SAMPLE INFORMATION

Sample Number	VCP435177	---	---	---
Sample Date	14 Sep 2023	---	---	---
Machine Hours	4069	---	---	---
Oil Hours	4000	---	---	---
Oil Changed	Changed	---	---	---
Sample Status	NORMAL	---	---	---



OIL CONDITION

Visc @ 40°C	cSt	█ 26.9	---	---	---
-------------	-----	--------	-----	-----	-----



CONTAMINATION

Silicon	ppm	█ 7	---	---	---
Sodium	ppm	█ 4	---	---	---
Potassium	ppm	█ 2	---	---	---



WEAR METALS

Iron	ppm	█ 159	---	---	---
Copper	ppm	█ 7	---	---	---
Lead	ppm	█ 0	---	---	---
Tin	ppm	█ 0	---	---	---
Aluminum	ppm	█ 4	---	---	---
Chromium	ppm	█ <1	---	---	---
Molybdenum	ppm	█ <1	---	---	---
Nickel	ppm	█ 0	---	---	---
Titanium	ppm	0	---	---	---
Silver	ppm	█ 0	---	---	---
Manganese	ppm	█ 5	---	---	---
Vanadium	ppm	0	---	---	---



ADDITIVES

Calcium	ppm	█ 91	---	---	---
Magnesium	ppm	█ 5	---	---	---
Zinc	ppm	█ 50	---	---	---
Phosphorus	ppm	█ 184	---	---	---
Barium	ppm	█ 0	---	---	---
Boron	ppm	█ 50	---	---	---

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the fluid. The condition of the fluid is acceptable for the time in service.

Depot: VOLVO3387
Unique No: 10656889
Signed: Wes Davis
Report Date: 20 Sep 2023



CONSTRUCTION EQUIPMENT



GRAPHS

