



# CONSTRUCTION EQUIPMENT

## 35408 VOLVO A25G 752732 - TRANSMISSION (AUTO)



**Sample No:** VCP415164  
**Oil Type:** VOLVO AUTOMATIC TRANSMISSION FLUID AT102  
**Job No:** 35408



### SAMPLE INFORMATION

Sample Number	VCP415164	---	---	---
Sample Date	14 Sep 2023	---	---	---
Machine Hours	2044	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Changed	---	---	---
Sample Status	NORMAL	---	---	---

### COWIN EQUIPMENT COMPANY

7950 PITTMAN AVE  
 PENSACOLA, FL  
 US 32534

Contact: HUGH DOBBS  
 HDOBBS@COWIN.COM  
 T: (850)479-3004  
 F: (850)474-1602



### OIL CONDITION

Visc @ 40°C	cSt	█ 29.7	---	---	---
-------------	-----	--------	-----	-----	-----



### CONTAMINATION

Silicon	ppm	█ 13	---	---	---
Sodium	ppm	█ 5	---	---	---
Potassium	ppm	█ 4	---	---	---



### WEAR METALS

Iron	ppm	█ 32	---	---	---
Copper	ppm	█ 19	---	---	---
Lead	ppm	█ 0	---	---	---
Tin	ppm	█ 4	---	---	---
Aluminum	ppm	█ 28	---	---	---
Chromium	ppm	█ <1	---	---	---
Molybdenum	ppm	█ 0	---	---	---
Nickel	ppm	█ 1	---	---	---
Titanium	ppm	█ 0	---	---	---
Silver	ppm	█ <1	---	---	---
Manganese	ppm	█ 4	---	---	---
Vanadium	ppm	█ 0	---	---	---



### ADDITIVES

Calcium	ppm	█ 67	---	---	---
Magnesium	ppm	█ <1	---	---	---
Zinc	ppm	█ 0	---	---	---
Phosphorus	ppm	█ 186	---	---	---
Barium	ppm	█ 0	---	---	---
Boron	ppm	█ 64	---	---	---

### Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the fluid. The condition of the fluid is acceptable for the time in service.

**Depot:** VOLVO8247  
**Unique No:** 10656891  
**Signed:** Wes Davis  
**Report Date:** 20 Sep 2023



# CONSTRUCTION EQUIPMENT



## VOLVO GRAPHS

