

# CONSTRUCTION EQUIPMENT SWA361236 VOLVO L90G 617437 - FRONT AXLE



Sample No: VCP401168

Oil Type: VOLVO WB 102

Job No: SWA361236

VOLVO	E INFORMATIO	V		
	INFURMATIUI			<u>.</u>
Sample Number		VCP401168	 	
Sample Date		15 Sep 2023	 	
Machine Hours		8105	 	
Oil Hours		8105	 	
Oil Changed		Changed	 	
Sample Status		NORMAL	 	
VOLVO				
OIL CON	IDITION			
Visc @ 40°C	cSt	<b>41.8</b>	 	
VOLVO	MINATION			
_	MINATION			
Silicon	ppm	<b>42</b>	 	
Sodium	ppm	<b>10</b>	 	
Potassium	ppm	<b>2</b>	 	
VOLVO				
WEAR N	METALS			
Iron	ppm	<b>9</b> 1	 	
Copper	ppm	<b>■7</b>	 	
Lead	ppm	<b>-&lt;1</b>	 	
Tin	ppm	<b>1</b>	 	
Aluminum	ppm	<b>-&lt;1</b>	 	
Chromium	ppm	<b>1</b>	 	
Molybdenum	ppm	<b>2</b>	 	
Nickel	ppm	<b>■</b> 0	 	
Titanium	ppm	<1	 	
Silver	ppm	0	 	
Manganese	ppm	<b>2</b>	 	
Vanadium	ppm	<1	 	
ADDITIV	VFC			
_				
Calcium	ppm	<b>4193</b>	 	
Magnesium	ppm	<b>25</b>	 	
Zinc	ppm	<b>1681</b>	 	
Phosphorus	ppm	<b>1360</b>	 	
Barium	ppm	<b>0</b>	 	
Boron	ppm	<b>166</b>	 	



#### **ALTA EQUIPMENT COMPANY**

5151 DR MARTIN LUTHER KING BLVD FORT MYERS, FL US 33905 Contact: TODD LARK tlark@altaequipfl.com

T:

F: (239)481-3302

### Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

 Depot:
 VOLVO0090

 Unique No:
 10657954

 Signed:
 Wes Davis

 Report Date:
 21 Sep 2023



## **CONSTRUCTION EQUIPMENT**





