

# CONSTRUCTION EQUIPMENT 9569 VOLVO A30G 742602 - TRANSMISSION (AUTO)



Sample No: VCP426156
Oil Type: VOLVO AT 102

**Job No:** 9569

SAMPL	E INFORMATION			
Sample Number	_	VCP426156	VCP349779	 
Sample Date		11 Sep 2023	18 Jan 2022	 
Machine Hours		3908	1901	 
Oil Hours		0	0	 
Oil Changed		Changed	Changed	 
Sample Status		NORMAL	NORMAL	 
OIL CON	IDITION			
Visc @ 40°C	cSt	<b>28.8</b>	<b>29.1</b>	 
VISC & 40 C	CSt		25.1	
VOLVO				
CONTAI	MINATION			
Silicon	ppm	■8	<b>1</b> 5	 
Sodium	ppm	<b>5</b>	7	 
Potassium	ppm	<b>5</b>	<b>2</b>	 
VOLVO	METALS			
WEAR	ALLI HEZ			
Iron	ppm	■29	<b>4</b> 2	 
Copper	ppm	<b>42</b>	<b>1</b> 74	 
Lead	ppm	■0	<b>-</b> <1	 
Tin	ppm	<b>10</b>	<b>1</b> 3	 
Aluminum	ppm	■36	<b>4</b> 2	 
Chromium	ppm	<b>■</b> <1	<b>-</b> <1	 
Molybdenum	ppm	<b>■</b> <1	<b>-</b> <1	 
Nickel	ppm	<b>■7</b>	<b>1</b> 2	 
Titanium	ppm	0	0	 
Silver	ppm	■0	0	 
Manganese	ppm	■3	<b>6</b>	 
Vanadium	ppm	<1	0	 
VOLVO				 
ADDITIV	VES			
Calcium	ppm	<b>114</b>	□ 147	 
Magnesium	ppm	<b>■</b> <1	1	 
Zinc	ppm	<b>0</b>	7	 
Phosphorus	ppm	<b>214</b>	■266	 
Barium	ppm	<b>0</b>	<b>2</b>	 
Boron	ppm	■81	■82	 



#### PLEASANT EXCAVATING COMPANY INC

24024 FREDERICK ROAD CLARKSBURG, MD US 20871 Contact: H TRENT HTRENT@PLEASANTS.ORG T: (301)252-5635 F:

### Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the fluid. The condition of the fluid is acceptable for the time in service.

Depot:PLECLAUnique No:10657975Signed:Don BaldridgeReport Date:22 Sep 2023



## **CONSTRUCTION EQUIPMENT**





