



# CONSTRUCTION EQUIPMENT

SWA362603 ML VOLVO L220H 2997 - COOLANT



**Sample No:** VCP431180  
**Oil Type:** VOLVO COOLANT VCS (YELLOW)  
**Job No:** SWA362603 ML



## SAMPLE INFORMATION

Sample Number	VCP431180	---	---	---
Sample Date	15 Sep 2023	---	---	---
Machine Hours	6431	---	---	---
Sample Status	NORMAL	---	---	---

**ALTA EQUIPMENT COMPANY - METRO WEST**  
 56195 PONTIAC TRAIL  
 NEW HUDSON, MI  
 US 48165  
 Contact: JEFF YAEK  
 jeff.yaek@altaequipment.com  
 T: (248)770-6328  
 F: x:



## COOLANT CONDITION

pH	Scale 0-14	■ 7.25	---	---	---
Reserve Alkalinity	Scale 0-20	---	---	---	---
Nitrites	ppm	■ NT	---	---	---
Percentage Glycol	%	■ 39.2	---	---	---
Freezing Point	°C	■ -11	---	---	---

## Diagnosis

No corrective action is recommended at this time. The fluid is suitable for further service. There is no indication of any contamination in the coolant. Carboxylate test failed. The glycol level is acceptable. The pH level of this fluid is within the acceptable limits.



## CONTAMINATION

Coolant Appearance	normal	---	---	---
Coolant Color	Yllow	---	---	---

**Depot:** VOLVO2990  
**Unique No:** 10658015  
**Signed:** Jonathan Hester  
**Report Date:** 22 Sep 2023



# CONSTRUCTION EQUIPMENT




## GRAPHS


### Iron/Tin/Silver




### Reserve Alkalinity



### Copper/Aluminum/Lead



### Freeze Point



### pH



### Nitrites

