



# CONSTRUCTION EQUIPMENT

## VOLVO A30G 740012 - BRAKE COOLING SYSTEM



**Sample No:** VCP435411  
**Oil Type:** CHEVRON 1000 THF  
**Job No:**



### VOLVO SAMPLE INFORMATION

Sample Number	VCP435411	---	---	---
Sample Date	18 Sep 2023	---	---	---
Machine Hours	5619	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Not Chngd	---	---	---
Sample Status	NORMAL	---	---	---

**ROMCO INC - AUSTIN BRANCH**  
 1150 WEST OLD SETTLERS BOULEVARD  
 ROUNDROCK, TX  
 US 78681  
 Contact: ED MAYES  
 EMAYES@ROMCO.COM  
 T: (737)204-9402  
 F: (512)388-2673

### VOLVO OIL CONDITION

Visc @ 40°C	cSt	■ 58.2	---	---	---
-------------	-----	--------	-----	-----	-----

### VOLVO CONTAMINATION

Silicon	ppm	■ 7	---	---	---
Sodium	ppm	■ 3	---	---	---
Potassium	ppm	■ <1	---	---	---

### Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

### VOLVO WEAR METALS

Iron	ppm	■ 2	---	---	---
Copper	ppm	■ 0	---	---	---
Lead	ppm	■ 0	---	---	---
Tin	ppm	■ 0	---	---	---
Aluminum	ppm	■ 1	---	---	---
Chromium	ppm	■ 0	---	---	---
Molybdenum	ppm	■ 14	---	---	---
Nickel	ppm	■ 0	---	---	---
Titanium	ppm	0	---	---	---
Silver	ppm	0	---	---	---
Manganese	ppm	■ 0	---	---	---
Vanadium	ppm	0	---	---	---

### VOLVO ADDITIVES

Calcium	ppm	■ 2509	---	---	---
Magnesium	ppm	■ 46	---	---	---
Zinc	ppm	■ 1157	---	---	---
Phosphorus	ppm	■ 932	---	---	---
Barium	ppm	■ 0	---	---	---
Boron	ppm	■ 14	---	---	---

**Depot:** VOLVO0088  
**Unique No:** 10659100  
**Signed:** Don Baldrige  
**Report Date:** 23 Sep 2023



# CONSTRUCTION EQUIPMENT



## GRAPHS

