



CONSTRUCTION EQUIPMENT

VOLVO A30G 740012 - REAR AXLE



Sample No: VCP435412
Oil Type: CHEVRON DELO GEAR ESI OIL 85W140
Job No:



SAMPLE INFORMATION

Sample Number	VCP435412	---	---	---
Sample Date	18 Sep 2023	---	---	---
Machine Hours	5619	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Not Chngd	---	---	---
Sample Status	NORMAL	---	---	---

ROMCO INC - AUSTIN BRANCH
 1150 WEST OLD SETTLERS BOULEVARD
 ROUNDROCK, TX
 US 78681
 Contact: ED MAYES
 EMAYES@ROMCO.COM
 T: (737)204-9402
 F: (512)388-2673

OIL CONDITION

Visc @ 40°C	cSt	172	---	---	---
-------------	-----	-----	-----	-----	-----

CONTAMINATION

Silicon	ppm	2	---	---	---
Sodium	ppm	<1	---	---	---
Potassium	ppm	2	---	---	---

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

WEAR METALS

Iron	ppm	0	---	---	---
Copper	ppm	0	---	---	---
Lead	ppm	0	---	---	---
Tin	ppm	0	---	---	---
Aluminum	ppm	1	---	---	---
Chromium	ppm	0	---	---	---
Molybdenum	ppm	6	---	---	---
Nickel	ppm	0	---	---	---
Titanium	ppm	0	---	---	---
Silver	ppm	0	---	---	---
Manganese	ppm	0	---	---	---
Vanadium	ppm	0	---	---	---

ADDITIVES

Calcium	ppm	884	---	---	---
Magnesium	ppm	35	---	---	---
Zinc	ppm	387	---	---	---
Phosphorus	ppm	913	---	---	---
Barium	ppm	0	---	---	---
Boron	ppm	145	---	---	---

Depot: VOLVO0088
Unique No: 10659101
Signed: Don Baldrige
Report Date: 23 Sep 2023



CONSTRUCTION EQUIPMENT



GRAPHS

