

## **CONSTRUCTION EQUIPMENT** VOLVO A45G 353274 - TRANSMISSION (AUTO)



## Sample No: VCP409515

VOLVO AUTOMATIC TRANSMISSION FLUID AT102

## Oil Type: Job No:

VOLVO						
	E INFORMATION		<u>.</u>	-	<u>_</u>	
Sample Number		VCP409515				
Sample Date		18 Sep 2023				ALTA EQUIPMENT COMPANY
Machine Hours		2337				5151 DR MARTIN LUTHER KING BLVD
Oil Hours		0				FORT MYERS, FL
Oil Changed		Changed				US 33905
Sample Status		ABNORMAL				Contact: TODD LARK
VOLVO						tlark@altaequipfl.com
OIL CON	NDITION					T: F: (239)481-3302
Visc @ 40°C	cSt	28.8				1. (233)401 3302
						- Diagnosis
CONTA	MINATION					Diagnosis
Silicon	ppm	13				Oil and filter change at the time of
Sodium	ppm	<b>6</b>				sampling has been noted. Resample at the next service interval to monitor.Moderate concentration of
Potassium	ppm	3				
lotassidili	ppin					visible metal present. All component
VOLVO						wear rates are normal. There is no
WEAR	METALS					indication of any contamination in
Iron	ppm	<b>46</b>				the fluid. The condition of the fluid is
Copper	ppm	33				acceptable for the time in service.
Lead	ppm	0				
Tin	ppm	5				
Aluminum	ppm	21				
Chromium	ppm	0				
Molybdenum	ppm	0				
Nickel	ppm	3				
Titanium	ppm	0				
Silver	ppm	0				
Manganese	ppm	4				
Vanadium	ppm	0				
ADDITI	VES					
Calcium	ppm	80				-
Magnesium	ppm	2				
Zinc	ppm	<b>40</b>				
Phosphorus	ppm	217				
Barium	ppm	0				
Boron	ppm	65				


Depot:	VOLVO0090
Unique No:	10659126
Signed:	Don Baldridge
Report Date:	23 Sep 2023

## **CONSTRUCTION EQUIPMENT**



GRAPHS

VOLVO



Contact/Location: TODD LARK - VOLVO0090