



# CONSTRUCTION EQUIPMENT

## VOLVO L90H 623696 - REAR AXLE



**Sample No:** VCP401453  
**Oil Type:** CHEVRON 1000 THF  
**Job No:**



### SAMPLE INFORMATION

Sample Number	VCP401453	---	---	---
Sample Date	30 Aug 2023	---	---	---
Machine Hours	14692	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Changed	---	---	---
Sample Status	NORMAL	---	---	---

**ROMCO INC - AUSTIN BRANCH**  
 1150 WEST OLD SETTLERS BOULEVARD  
 ROUNDROCK, TX  
 US 78681  
 Contact: MATT MACHANN  
 mmachann@romco.com  
 T: (832)270-0121  
 F: (512)845-7565



### OIL CONDITION

Visc @ 40°C	cSt	█ 59.8	---	---	---
-------------	-----	--------	-----	-----	-----



### CONTAMINATION

Silicon	ppm	█ 6	---	---	---
Sodium	ppm	█ 0	---	---	---
Potassium	ppm	█ 3	---	---	---

### Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.



### WEAR METALS

Iron	ppm	█ 21	---	---	---
Copper	ppm	█ 1	---	---	---
Lead	ppm	█ 0	---	---	---
Tin	ppm	█ <1	---	---	---
Aluminum	ppm	█ 1	---	---	---
Chromium	ppm	█ <1	---	---	---
Molybdenum	ppm	█ 11	---	---	---
Nickel	ppm	█ <1	---	---	---
Titanium	ppm	<1	---	---	---
Silver	ppm	0	---	---	---
Manganese	ppm	█ <1	---	---	---
Vanadium	ppm	0	---	---	---



### ADDITIVES

Calcium	ppm	█ 2844	---	---	---
Magnesium	ppm	█ 41	---	---	---
Zinc	ppm	█ 1120	---	---	---
Phosphorus	ppm	█ 941	---	---	---
Barium	ppm	█ 0	---	---	---
Boron	ppm	█ 25	---	---	---

**Depot:** VOLVO0088  
**Unique No:** 10660003  
**Signed:** Wes Davis  
**Report Date:** 23 Sep 2023



# CONSTRUCTION EQUIPMENT



## GRAPHS

