

## CONSTRUCTION EQUIPMENT VOLVO L90H 625154 - REAR AXLE



Sample No: VCP392768

Oil Type: CHEVRON 1000 THF

Job No:

VOLVO					
SAMPLE	INFORMATION				
Sample Number	-	VCP392768			
Sample Date		31 Aug 2023			
Machine Hours		7575			
Oil Hours		0			
Oil Changed		Changed			
Sample Status		NORMAL			
OIL CONDITION					
Visc @ 40°C	cSt	<b>50.1</b>			
		_			
VOLVO	MATION				
CONTAM	MATIUN		-		
Silicon	ppm	<b>□</b> 7			
Sodium	ppm	■0			
Potassium	ppm	<b>■</b> 2			
VOLVO					
WEAR METALS					
Iron	ppm	<b>■71</b>			
Copper	ppm	<b>■</b> 5			
Lead	ppm	<b>■</b> <1			
Tin	ppm	<b>■</b> <1			
Aluminum	ppm	■1			
Chromium	ppm	<b>■</b> <1			
Molybdenum	ppm	<b>■</b> 5			
Nickel	ppm	<b>■</b> <1			
Titanium	ppm	0			
Silver	ppm	0			
Manganese	ppm	■1			
Vanadium	ppm	0			
VOLVO					
ADDITIVI	2				
Calcium	ppm	<b>2271</b>			
Magnesium	ppm	<b>22</b>			
Zinc	ppm	<b>1086</b>			
Phosphorus	ppm	■968			
Barium	ppm	<b>■</b> 0			
Boron	ppm	<b>14</b>			



# ROMCO INC - AUSTIN BRANCH 1150 WEST OLD SETTLERS BOULEVARD ROUNDROCK, TX US 78681 Contact: ED MAYES EMAYES@ROMCO.COM

T: (737)204-9402 F: (512)388-2673

#### Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:VOLVO0088Unique No:10660008Signed:Wes DavisReport Date:23 Sep 2023



### **CONSTRUCTION EQUIPMENT**





