

CONSTRUCTION EQUIPMENT 11040 VOLVO L90H 624901 - REAR AXLE



Sample No: VCP441840

Oil Type: TRANSAXLE OIL SAE 75W80

Job No: 11040

SAMPLE	NFORMATION				
Sample Number	•	VCP441840	VCP399146	VCP365721	VCP361449
Sample Date		11 Sep 2023	07 Mar 2023	22 Nov 2022	14 Jul 2022
Machine Hours		8453	7635	7189	6680
Oil Hours		0	1000	0	1000
Oil Changed		Not Changd	Not Changd	Not Changd	Not Changd
Sample Status		ABNORMAL	NORMAL	NORMAL	NORMAL
OIL COND	ITION				
Visc @ 40°C	cSt	41.9	42.0	42.2	41.5
		_	_	_	_
CONTAMI	NATION				
Silicon	ppm	12	1 2	1 2	1 3
Sodium	ppm	7	6	■ <1	9
Potassium	ppm	■3	■ 3	□0	□0
	r r	_			
WEAR METALS					
Iron	ppm	159	□157	153	□146
Copper	ppm	6	6	6	5
Lead	ppm	■<1	■0	0	 <1
Tin	ppm		- <1	■0	1
Aluminum	ppm	2	■ 3	1	1
Chromium	ppm	1	2	1	_2
Molybdenum	ppm	■2	2	1	2
Nickel	ppm	■<1	- <1	0	0
Titanium	ppm	<1	<1	0	0
Silver	ppm	0	0	0	<1
Manganese	ppm	■ 2	2	2	2
Vanadium	ppm	0	0	0	0
VOLVO					
ADDITIVE	2				
Calcium	ppm	■3767	3823	■3923	4096
	ppiii	_			
Magnesium	ррт	13	14	11	16
Magnesium Zinc		□ 13 □ 1527		□ 11 □ 1439	1606
Zinc Phosphorus	ppm	13 1527 1220	14 1509 1236	11 1439 1219	1606 1268
Zinc	ppm ppm	□ 13 □ 1527	14 1509	□ 11 □ 1439	1606



WASTE MGMT GROWS LANDFILL 1121 BORDENTOWN ROAD

MORRISVILLE, PA US 19067 Contact: JIM

T: (215)736-9490 F: (215)736-0662

Diagnosis

No corrective action is recommended at this time. Resample at the next service interval to monitor.All component wear rates are normal. Moderate concentration of visible dirt/debris present in the oil. The condition of the oil is acceptable for the time in service.

Depot:WASMORUnique No:10660025Signed:Don BaldridgeReport Date:24 Sep 2023



CONSTRUCTION EQUIPMENT





