



CONSTRUCTION EQUIPMENT

SW-24201-2 VOLVO ECR145E 316420 - REAR RIGHT FINAL DRIVE



Sample No: VCP432508
Oil Type: VOLVO PREMIUM GEAR OIL 80W-90 GL-5
Job No: SW-24201-2



SAMPLE INFORMATION

Sample Number	VCP432508	---	---	---
Sample Date	18 Sep 2023	---	---	---
Machine Hours	555	---	---	---
Oil Hours	555	---	---	---
Oil Changed	Changed	---	---	---
Sample Status	ABNORMAL	---	---	---

ARNOLD MACHINERY COMPANY
 2975 WEST 2100 SOUTH
 SALT LAKE CITY, UT
 US 84119
 Contact: TONY PAYAN
 tpayan@arnoldmachinery.com
 T: (801)972-4000
 F: (801)975-9434



OIL CONDITION

Visc @ 40°C	cSt	█ 137	---	---	---
-------------	-----	-------	-----	-----	-----



CONTAMINATION

Silicon	ppm	█ 16	---	---	---
Sodium	ppm	█ 5	---	---	---
Potassium	ppm	█ 1	---	---	---

Diagnosis

The oil change at the time of sampling has been noted. No corrective action is recommended at this time. Resample at the next service interval to monitor. The tin level is abnormal. All other metal levels are typical for a new component breaking in. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.



WEAR METALS

Iron	ppm	█ 364	---	---	---
Copper	ppm	█ 1	---	---	---
Lead	ppm	█ 0	---	---	---
Tin	ppm	▲ 32	---	---	---
Aluminum	ppm	█ 2	---	---	---
Chromium	ppm	█ 7	---	---	---
Molybdenum	ppm	█ <1	---	---	---
Nickel	ppm	█ <1	---	---	---
Titanium	ppm	<1	---	---	---
Silver	ppm	0	---	---	---
Manganese	ppm	█ 8	---	---	---
Vanadium	ppm	0	---	---	---



ADDITIVES

Calcium	ppm	█ 40	---	---	---
Magnesium	ppm	█ <1	---	---	---
Zinc	ppm	█ 41	---	---	---
Phosphorus	ppm	█ 324	---	---	---
Barium	ppm	█ 0	---	---	---
Boron	ppm	█ 0	---	---	---

Depot: VOLVO8770
Unique No: 10661393
Signed: Don Baldrige
Report Date: 26 Sep 2023



CONSTRUCTION EQUIPMENT



GRAPHS

