



CONSTRUCTION EQUIPMENT

VOLVO L90H 625477 - REAR LEFT FINAL DRIVE



Sample No: VCP323627
Oil Type: TDTO FLUID SAE 10W
Job No:



SAMPLE INFORMATION

Sample Number	VCP323627	---	---	---
Sample Date	30 Aug 2023	---	---	---
Machine Hours	5362	---	---	---
Oil Hours	0	---	---	---
Oil Changed	N/A	---	---	---
Sample Status	NORMAL	---	---	---

ROMCO INC - AUSTIN BRANCH
 1150 WEST OLD SETTLERS BOULEVARD
 ROUNDROCK, TX
 US 78681
 Contact: MATT MACHANN
 mmachann@romco.com
 T: (832)270-0121
 F: (512)845-7565



OIL CONDITION

Visc @ 40°C	cSt	█ 47.8	---	---	---
-------------	-----	--------	-----	-----	-----



CONTAMINATION

Silicon	ppm	█ 6	---	---	---
Sodium	ppm	█ 0	---	---	---
Potassium	ppm	█ 2	---	---	---



WEAR METALS

Iron	ppm	█ 22	---	---	---
Copper	ppm	█ 8	---	---	---
Lead	ppm	█ <1	---	---	---
Tin	ppm	█ <1	---	---	---
Aluminum	ppm	█ 2	---	---	---
Chromium	ppm	█ <1	---	---	---
Molybdenum	ppm	█ 6	---	---	---
Nickel	ppm	█ 0	---	---	---
Titanium	ppm	0	---	---	---
Silver	ppm	0	---	---	---
Manganese	ppm	█ <1	---	---	---
Vanadium	ppm	0	---	---	---



ADDITIVES

Calcium	ppm	█ 2436	---	---	---
Magnesium	ppm	█ 25	---	---	---
Zinc	ppm	█ 1163	---	---	---
Phosphorus	ppm	█ 1004	---	---	---
Barium	ppm	█ 0	---	---	---
Boron	ppm	█ 19	---	---	---

Diagnosis

Resample at the next service interval to monitor. The fluid was not specified, however, a fluid match indicates that this fluid is (GENERIC) TDTO FLUID SAE 10W. Please confirm.
 All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: VOLVO0088
Unique No: 10661414
Signed: Wes Davis
Report Date: 26 Sep 2023



CONSTRUCTION EQUIPMENT



GRAPHS

