

## CONSTRUCTION EQUIPMENT VOLVO L90H 625477 - REAR RIGHT FINAL DRIVE



Sample No: VCP323618

Oil Type: TDTO FLUID SAE 10W

Job No:

| VOLVO         |             |               |  |  |  |
|---------------|-------------|---------------|--|--|--|
| SAMPLE        | INFORMATION | V             |  |  |  |
| Sample Number |             | VCP323618     |  |  |  |
| Sample Date   |             | 30 Aug 2023   |  |  |  |
| Machine Hours |             | 5362          |  |  |  |
| Oil Hours     |             | 0             |  |  |  |
| Oil Changed   |             | N/A           |  |  |  |
| Sample Status |             | NORMAL        |  |  |  |
|               |             |               |  |  |  |
| OIL CONDITION |             |               |  |  |  |
| Visc @ 40°C   | cSt         | <b>47.9</b>   |  |  |  |
| V13C @ 40 C   | CSt         | <b>47.5</b>   |  |  |  |
| VOLVO         |             |               |  |  |  |
| CONTAN        | MINATION    |               |  |  |  |
| Silicon       | ppm         | ■8            |  |  |  |
| Sodium        | ppm         | <b>■</b> 0    |  |  |  |
| Potassium     | ppm         | <b>1</b>      |  |  |  |
|               |             |               |  |  |  |
| WEAR METALS   |             |               |  |  |  |
| Iron          | ppm         | <b>26</b>     |  |  |  |
| Copper        | ppm         | <b>■8</b>     |  |  |  |
| Lead          | ppm         | <b>■&lt;1</b> |  |  |  |
| Tin           | ppm         | <b>■&lt;1</b> |  |  |  |
| Aluminum      | ppm         | ■3            |  |  |  |
| Chromium      | ppm         | <b>■&lt;1</b> |  |  |  |
| Molybdenum    | ppm         | <b>7</b>      |  |  |  |
| Nickel        | ppm         | <b>■</b> 0    |  |  |  |
| Titanium      | ppm         | 0             |  |  |  |
| Silver        | ppm         | 0             |  |  |  |
| Manganese     | ppm         | <b>■&lt;1</b> |  |  |  |
| Vanadium      | ppm         | 0             |  |  |  |
|               |             |               |  |  |  |
| ADDITIV       | IES         |               |  |  |  |
| Calcium       | ppm         | <b>2722</b>   |  |  |  |
| Magnesium     | ppm         | <b>29</b>     |  |  |  |
| Zinc          | ppm         | <b>1316</b>   |  |  |  |
| Phosphorus    | ppm         | <b>1111</b>   |  |  |  |
| Barium        | ppm         | <b>■</b> 0    |  |  |  |
| Boron         | ppm         | <b>21</b>     |  |  |  |
|               |             |               |  |  |  |



ROMCO INC - AUSTIN BRANCH
1150 WEST OLD SETTLERS BOULEVARD
ROUNDROCK, TX
US 78681
Contact: MATT MACHANN
mmachann@romco.com
T: (832)270-0121

F: (512)845-7565

## Diagnosis

Resample at the next service interval to monitor. The fluid was not specified, however, a fluid match indicates that this fluid is (GENERIC) TDTO FLUID SAE 10W. Please confirm.

All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:VOLVO0088Unique No:10661415Signed:Wes DavisReport Date:26 Sep 2023



## **CONSTRUCTION EQUIPMENT**





## GRAPHS

