CONSTRUCTION EQUIPMENT 19695 MMA-CLACKS VOLVO A45G 352449 - COOLANT



Sample No: VCP415496 **Oil Type:**

VOLVO

VOLVO COOLANT VCS (YELLOW) Job No: 19695 MMA-CLACKS

	_
VOLV	0

VOLVO							
SAMPLE INFORMATION							
Sample Number		VCP415496					
Sample Date		13 Sep 2023					
Machine Hours		962					
Sample Status		NORMAL					
COOLANT CONDITION							
рН	Scale 0-14	7.74					
Reserve Alkalinity	Scale 0-20						
Nitrites	ppm	NT NT					
Percentage Glycol	%	43.6					
Freezing Point	°C	-19					
CONTAMINATION							
		• .	. .	-			
Coolant Appearance		normal					
Coolant Color		Yllow					



117 - ASCENDUM MACHINERY INC - GREENVILLE 2002 N GREENE ST

GREENVILLE, NC US 27834 Contact: BRANDON JENKINS BRANDON, JENKINS@ASCENDUMMACHINERY.COM T: F: (704)494-8197

limits.

Diagnosis No corrective action is recommended at this time. The fluid is suitable for further service. There is no indication of any contamination in the coolant. Carboxylate test failed. The glycol level is acceptable. The pH level of this fluid is within the acceptable

Depot: VOLVO8769 Unique No: 10662780 Signed: Doug Bogart Report Date: 28 Sep 2023


CONSTRUCTION EQUIPMENT



GRAPHS

Iron/Tin/Silver

VOLVO



Contact/Location: BRANDON JENKINS - VOLVO8769