

## CONSTRUCTION EQUIPMENT VOLVO ECR235E 314672 - SWING DRIVE



Sample No: VCE164995

Oil Type: VOLVO PREMIUM GEAR OIL 80W-90 GL-5

Job No:

SAMPLE	INFORMATIO	N		
Sample Number		VCE164995	 	
Sample Number		19 Sep 2023	 	
Machine Hours		997	 	
Oil Hours		0	 	
Oil Changed		Changed	 	
Sample Status		ABNORMAL	 	
VOLVO				
OIL CON	DITION			
Visc @ 40°C	cSt	<b>172</b>	 	
VOLVO				
CONTAN	MINATION			
Water	%	■ 0.102	 	
Silicon	ppm	<b>12</b>	 	
Sodium	ppm	<b>■&lt;1</b>	 	
Potassium	ppm	<b>■</b> 0	 	
WEAR N	ACTAL C			
_	IE I WEZ			
Iron	ppm	■215	 	
Copper	ppm	<u> </u>	 	
Lead	ppm	<b>2</b>	 	
Tin	ppm	<b>■&lt;1</b>	 	
Aluminum	ppm	■5	 	
Chromium	ppm	<b>2</b>	 	
Molybdenum	ppm	<b>0</b>	 	
Nickel	ppm	<b>■</b> 0	 	
Titanium	ppm	0	 	
Silver	ppm	0	 	
Manganese	ppm	<b>6</b>	 	
Vanadium	ppm	0	 	
ADDITIV	IFS			
_	_			
Calcium	ppm	<b>4</b>	 	
Magnesium	ppm	<b>0</b>	 	
Zinc	ppm	■ 50	 	
Phosphorus	ppm	<b>294</b>	 	
Barium	ppm	<b>0</b>	 	
Boron	ppm	■0	 	



THE GW VAN KEPPEL CO MAIN 1801 NORTH 9TH STREET KANSAS CITY, KS US 66101 Contact: BRIAN LODERHOSE bloderhose@vankeppel.com T:

## Diagnosis

F: (913)281-4815

The oil change at the time of sampling has been noted. Resample at the next service interval to monitor. The copper level is abnormal. All other component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:VOLVO0111Unique No:10668433Signed:Jonathan HesterReport Date:28 Sep 2023



## **CONSTRUCTION EQUIPMENT**





