

CONSTRUCTION EQUIPMENT 595224 VOLVO A40G 352787 - FRONT AXLE



Sample No: VCP417021

Oil Type: VOLVO PREMIUM GEAR OIL 85W-140 GL-5

Job No: 595224

SAMPLE	INFORMATION				
Sample Number		VCP417021	VCP350113	VCP351162	
Sample Date		25 Aug 2023	30 Jun 2022	20 Jan 2022	
Machine Hours		4246	1962	940	
Oil Hours		3246	1000	940	
Oil Changed		Changed	Changed	Changed	
Sample Status		NORMAL	NORMAL	ATTENTION	
OIL CON	DITION				
Visc @ 40°C	cSt	223	<u></u> 261	△ 50.1	
VISC @ 40 C	CSL	223	<u> </u>	50.1	
VOLVO					
CONTAM	IINATION				
Silicon	ppm	■ 9	2	5	
Sodium	ppm	■ 0	0	■3	
Potassium	ppm	■ 0	1	4	
WEAR M	IETALS				
Iron	ppm	108	■ 51	■385	
Copper	ppm	■ 4	- <1	■3	
Lead	ppm	■0	□0		
Tin	ppm	■<1	0	<u> </u>	
Aluminum	ppm	■ 2	< 1	2	
Chromium	ppm	■ 1	- <1	6	
Molybdenum	ppm	■2	1	■8	
Nickel	ppm	■0	0	2	
Titanium	ppm	0	0	0	
Silver	ppm	0	0	0	
Manganese	ppm	4	2	□ 14	
Vanadium	ppm	0	0	0	
VOLVO					
ADDITIV	ES				
Calcium	ppm	25	7 4	■36	
Magnesium	ppm	-<1	5	0	
Zinc	ppm	67	■80	△ 15	
Phosphorus	ppm	1023	■876	△ 2769	
Barium	ppm	0	2	0	
Boron	ppm	180	169	▲ 283	



RIPA AND ASSOCIATES

10149 FISHER AVENUE TAMPA, FL US 33619 Contact: PM Services PMServices@ripaconstruction.com T·

Diagnosis

F:

Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:RIPTAMUnique No:10669040Signed:Wes DavisReport Date:28 Sep 2023



CONSTRUCTION EQUIPMENT





