



# CONSTRUCTION EQUIPMENT

606083 GERDAU VOLVO L350H 1221 - COOLANT



**Sample No:** VCP431150  
**Oil Type:** VOLVO COOLANT VCS (YELLOW)  
**Job No:** 606083 GERDAU



## SAMPLE INFORMATION

|               |             |     |     |     |
|---------------|-------------|-----|-----|-----|
| Sample Number | VCP431150   | --- | --- | --- |
| Sample Date   | 20 Sep 2023 | --- | --- | --- |
| Machine Hours | 6073        | --- | --- | --- |
| Sample Status | NORMAL      | --- | --- | --- |

**ALTA EQUIPMENT COMPANY - METRO WEST**  
56195 PONTIAC TRAIL  
NEW HUDSON, MI  
US 48165  
Contact: PAUL CONZ  
paul.conz@altg.com  
T: (313)348-8861  
F: (248)356-2029



## COOLANT CONDITION

|                    |            |        |     |     |     |
|--------------------|------------|--------|-----|-----|-----|
| pH                 | Scale 0-14 | ■ 9.72 | --- | --- | --- |
| Reserve Alkalinity | Scale 0-20 | ---    | --- | --- | --- |
| Nitrites           | ppm        | ■ NT   | --- | --- | --- |
| Percentage Glycol  | %          | ■ 47.6 | --- | --- | --- |
| Freezing Point     | °C         | ■ -28  | --- | --- | --- |

## Diagnosis

No corrective action is recommended at this time. The fluid is suitable for further service. There is no indication of any contamination in the coolant. Carboxylate test failed. The glycol level is acceptable. The pH level of this fluid is within the acceptable limits.



## CONTAMINATION

|                    |        |     |     |     |
|--------------------|--------|-----|-----|-----|
| Coolant Appearance | normal | --- | --- | --- |
| Coolant Color      | Yllow  | --- | --- | --- |

**Depot:** VOLVO2990  
**Unique No:** 10669194  
**Signed:** Jonathan Hester  
**Report Date:** 03 Oct 2023



# CONSTRUCTION EQUIPMENT




## VOLVO GRAPHS


### Iron/Tin/Silver




### Reserve Alkalinity




### Copper/Aluminum/Lead



### Freeze Point



### pH



### Nitrites

