CONSTRUCTION EQUIPMENT 594615 APTIM VOLVO A30G 740273 - COOLANT



Sample No: VCP414200 VOLVO COOLANT VCS (YELLOW) **Oil Type:** Job No:

VOLVO

594615 APTIM

SAMPLE I	NFORMATION			
Sample Number		VCP414200	 	
Sample Date		22 Aug 2023	 	
Machine Hours		11091	 	
Sample Status		NORMAL	 	
COOLANT	CONDITION			
рН	Scale 0-14	7.42	 	
Reserve Alkalinity	Scale 0-20		 	
Nitrites	ppm	NT	 	
Percentage Glycol	%	45.0	 	
Freezing Point	°C	-24	 	
CONTAMIN	NATION		 	
Coolant Appearance	-	normal	 	
Coolant Color		Yllow	 	



ALTA EQUIPMENT/FLAGLER CONSTRUCTION EQUIPMENT LLC

8418 PALM RIVER ROAD TAMPA, FL US 33619 Contact: JOHN FARDELLA JFARDELLA@ALTAEQUIPFL.COM T: (813)630-0077 F: (813)630-2233

Diagnosis

No corrective action is recommended at this time. The fluid is suitable for further service. There is no indication of any contamination in the coolant. Carboxylate test failed. The glycol level is acceptable. The pH level of this fluid is within the acceptable limits.

Depot: VOLVO0093 Unique No: 10669195 Signed: Jonathan Hester Report Date: 03 Oct 2023


CONSTRUCTION EQUIPMENT



GRAPHS

Iron/Tin/Silver

VOLVO



Contact/Location: JOHN FARDELLA - VOLVO0093