

## **CONSTRUCTION EQUIPMENT**

607874 ASH GROVE VOLVO L180H 5419 - HYDRAULIC SYSTEM

Sample No: VCP440984

Oil Type: VOLVO SUPER HYDRAULIC OIL 46

**Job No:** 607874 ASH GROVE





#### ALTA EQUIPMENT/FLAGLER EQUIPMENT LLC

9601 BOGGY CREEK RD ORLANDO, FL US 32824 Contact: Robert LaPlante robert.laplante@altg.com T: (407)508-9736 F: (407)659-8720

### Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. The system cleanliness is acceptable for your target ISO 4406 cleanliness code. The system and fluid cleanliness is acceptable. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

 Depot:
 VOLVO0096

 Unique No:
 10670702

 Signed:
 Wes Davis

 Report Date:
 29 Sep 2023

ppm

ppm

ppm

ppm

**473** 

**370** 

**0** 

**0** 

Zinc

Barium

Boron

Phosphorus



# **CONSTRUCTION EQUIPMENT**





#### GRAPHS

