

# CONSTRUCTION EQUIPMENT VOLVO L70E 67918 - TRANSMISSION (AUTO)



Sample No: VCP0007365
Oil Type: DEXRON III

Job No:

| SAMPLE        | E INFORMATIO | N             |      |  |
|---------------|--------------|---------------|------|--|
| Sample Number | •            | VCP0007365    | <br> |  |
| Sample Date   |              | 25 Sep 2023   | <br> |  |
| Machine Hours |              | 0             | <br> |  |
| Oil Hours     |              | 0             | <br> |  |
| Oil Changed   |              | N/A           | <br> |  |
| Sample Status |              | NORMAL        | <br> |  |
|               |              |               |      |  |
| OIL CON       | DITION       |               |      |  |
| Visc @ 40°C   | cSt          | □30.4         | <br> |  |
|               | 001          |               |      |  |
| VOLVO         | 4018 E1611   |               |      |  |
| LONTAN        | MINATION     |               |      |  |
| Silicon       | ppm          | ■3            | <br> |  |
| Sodium        | ppm          | <b>1</b>      | <br> |  |
| Potassium     | ppm          | <b>■&lt;1</b> | <br> |  |
|               |              |               |      |  |
| WEAR N        | METALS       |               |      |  |
| Iron          | ppm          | <b>4</b>      | <br> |  |
| Copper        | ppm          | <b>2</b>      | <br> |  |
| Lead          | ppm          | <b>0</b>      | <br> |  |
| Tin           | ppm          | <b>0</b>      | <br> |  |
| Aluminum      | ppm          | <b>0</b>      | <br> |  |
| Chromium      | ppm          | ■0            | <br> |  |
| Molybdenum    | ppm          | <b>■&lt;1</b> | <br> |  |
| Nickel        | ppm          | <b>■</b> 0    | <br> |  |
| Titanium      | ppm          | 0             | <br> |  |
| Silver        | ppm          | ■0            | <br> |  |
| Manganese     | ppm          | <b>■</b> 0    | <br> |  |
| Vanadium      | ppm          | 0             | <br> |  |
|               |              |               | <br> |  |
| ADDITIV       | VES          |               |      |  |
| Calcium       | ppm          | <b>224</b>    | <br> |  |
| Magnesium     | ppm          | <b>4</b>      | <br> |  |
| Zinc          | ppm          | <b>■</b> 79   | <br> |  |
| Phosphorus    | ppm          | <b>243</b>    | <br> |  |
| Barium        | ppm          | <b>2</b>      | <br> |  |
| Boron         | ppm          | <b>9</b> 5    | <br> |  |
|               |              | _             |      |  |



#### **ALTA EQUIPMENT COMPANY**

8750 PHILIPS HWY JACKSONVILLE, FL US 32256

Contact: TECHNICIAN ACCOUNT catherine.anastasio@wearcheck.com T:

F: (904)737-1260

### Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the fluid. The condition of the fluid is acceptable for the time in service.

Depot:VOLVO0092Unique No:10670903Signed:Don BaldridgeReport Date:01 Oct 2023

Submitted By: TECHNICIAN ACCOUNT



## **CONSTRUCTION EQUIPMENT**





