



# CONSTRUCTION EQUIPMENT

WASTE CONNECTION VOLVO L110H 631413 - TRANSMISSION (AUTO)



**Sample No:** VCP425836  
**Oil Type:** VOLVO  
**Job No:** WASTE CONNECTION



## SAMPLE INFORMATION

Sample Number	VCP425836	---	---	---
Sample Date	27 Sep 2023	---	---	---
Machine Hours	20428	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Changed	---	---	---
Sample Status	NORMAL	---	---	---

ALTA EQUIPMENT/FLAGLER CONSTRUCTION EQUIPMENT LLC  
8418 PALM RIVER ROAD  
TAMPA, FL  
US 33619  
Contact: KENNY HANEY  
khaney@flaglerce.com  
T: (813)630-0077  
F: (813)630-2233



## OIL CONDITION

Visc @ 40°C	cSt	■ 28.4	---	---	---
-------------	-----	--------	-----	-----	-----



## CONTAMINATION

Silicon	ppm	■ 2	---	---	---
Sodium	ppm	■ 2	---	---	---
Potassium	ppm	■ 0	---	---	---

## Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the fluid. The condition of the fluid is acceptable for the time in service.



## WEAR METALS

Iron	ppm	■ 6	---	---	---
Copper	ppm	■ 1	---	---	---
Lead	ppm	■ 0	---	---	---
Tin	ppm	■ <1	---	---	---
Aluminum	ppm	■ 4	---	---	---
Chromium	ppm	■ 0	---	---	---
Molybdenum	ppm	<1	---	---	---
Nickel	ppm	■ 0	---	---	---
Titanium	ppm	<1	---	---	---
Silver	ppm	■ 0	---	---	---
Manganese	ppm	<1	---	---	---
Vanadium	ppm	0	---	---	---



## ADDITIVES

Calcium	ppm	92	---	---	---
Magnesium	ppm	12	---	---	---
Zinc	ppm	12	---	---	---
Phosphorus	ppm	207	---	---	---
Barium	ppm	0	---	---	---
Boron	ppm	87	---	---	---

**Depot:** VOLVO0093  
**Unique No:** 10671454  
**Signed:** Don Baldrige  
**Report Date:** 01 Oct 2023



# CONSTRUCTION EQUIPMENT



## GRAPHS

