

## **CONSTRUCTION EQUIPMENT**

607957 ASH GROVE VOLVO EC480 315369 - HYDRAULIC SYSTEM

Sample No: VCP440295

Chromium

Nickel

Silver

Titanium

Manganese

Vanadium

Calcium

Zinc

Barium

Boron

Magnesium

Phosphorus

Molybdenum

Oil Type: VOLVO SUPER HYDRAULIC OIL 46

**Job No:** 607957 ASH GROVE

VOLVO					
	NFORMATION				
Sample Number	-	VCP440295			
Sample Date		26 Sep 2023			
Machine Hours		595			
Oil Hours		0			
Oil Changed		Not Changd			
Sample Status		NORMAL			
OIL CONDITION					
Visc @ 40°C	cSt	<b>41.6</b>			
Acid Number (AN)	mg KOH/g	■ 0.50			
CONTAMINATION					
Particles >4µm	-	<b>15798</b>			
Particles >6µm		■3629			
Particles >14µm		<b>163</b>			
ISO 4406:1999 (c)		21/19/15			
Silicon	ppm	<b>■</b> 3			
Sodium	ppm	<b>■&lt;1</b>			
Potassium	ppm	<b>0</b>			
WEAR ME	TALS				
Iron	ppm	<b>■</b> <1			
Copper	ppm	<b>6</b>			
Lead	ppm	<b>0</b>			
Tin	ppm	■0			
Aluminum	ppm	<b>■&lt;1</b>			



ALTA EQUIPMENT/FLAGLER EQUIPMENT LLC
9601 BOGGY CREEK RD
ORLANDO, FL
US 32824
Contact: Robert LaPlante
robert.laplante@altg.com
T: (407)508-9736
F: (407)659-8720

## Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. The system cleanliness is acceptable for your target ISO 4406 cleanliness code. The system and fluid cleanliness is acceptable. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

VOLVO0096		
10671852		
Wes Davis		
02 Oct 2023		

**0** 

**0** 

**0** 

0

0

0

**92** 

**3** 

**0** 

**0** 

**■**504 **■**402

**0** 

ppm

**ADDITIVES** 



## **CONSTRUCTION EQUIPMENT**





## GRAPHS

